## **Vallabh Enterprises**

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Details : VE11908							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9820536525						
Technician Name :	Atique Salmani			Tec	hnician Mobile :	<b>Mobile :</b> 8080922984	
Ticket Type :	Complain	Date & Time :		15-	06-2024 12:52:55		
Vendor Details :							
Company Name/Client Name :	Vireshwar Heights	Customer's Mobile :		: 982	20536525	Name :	Dhiru Sir
Address:							
Mumbai,,,,Maharashtra							
AMC Details :							
Expiry Date :	01-01-1970 05:30:00		Тур	e:			
<b>Product Name:</b>	CCTV						
Complain:	need to show to client newly installed cameras						
Technician Comment :	All cameras was lagging So All cameras resolution was $2560*1440$ Now changed it $2304*1296$ Frame 20 quality higher bit 2 Mbps And also changed 1metr new pachcode NVR to swich . NVR pass .Vallabh@12 Camera pass Vallabh12 NVR ip $192.168.29.166$						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	All cameras was lagging So All cameras resolution was $2560*1440$ Now changed it $2304*1296$ Frame 20 quality higher bit 2 Mbps And also changed 1metr new pachcode NVR to swich . NVR pass .Vallabh@12 Camera pass Vallabh12 NVR ip 192.168.29.166						
<b>Status History :</b>	Date Time	Technician Name	Status		Remark		Sign
		Atique Salmani		pleted	All cameras was lagging So All cameras resolution was 2560*1440 Now changed it 2304*1296 Frame 20 quality higher bit 2 Mbps And also changed 1metr new pachcode NVR to swich . NVR pass .Vallabh@12 Camera pass Vallabh12 NVR ip 192.168.29.166		Jeans
		tique New almani					-
Previous	Date Time Technician Name			Remark			
Complain History :	07-06-2024 01:51:06						
	06-06-2024 11:24:36	06-2024 11:24:36 Neeraj Chauh		2 nos Staircase camera install and angle set and 2 - nos out door buttet camera dislocated angle set and 1 nos hidmi switcher install and 601 intercom phone speaker not working okk			