




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE15906</b>																																			
<b>Priority :</b>	Low																																		
<b>Created By :</b>	Admin - Apurva Vajaria																																		
<b>Complaint Mob. No. :</b>	9619474819																																		
<b>Technician Name :</b>	Maroof Raza		<b>Technician Mobile :</b>	7761863562																															
<b>Ticket Type :</b>	New Installation	<b>Date &amp; Time :</b>	29-09-2025 12:25:44																																
<b>Vendor Details :</b>																																			
Company Name/Client Name :	Shree Ram Welfare Society High School	Customer's Mobile :	9619474819	Name :	Dinesh Sir																														
<b>Address :</b>																																			
Mumbai , , , 400058 , Maharashtra																																			
<b>AMC Details :</b>																																			
Expiry Date :	31-05-2021 12:00:00		Type :	Non-Comprehensive																															
<b>Product Name :</b>	CCTV																																		
<b>Complain :</b>	5 camera installation need to do																																		
<b>Technician Comment :</b>	5 camera install done working camer no A1,A2,4C,4B, DMLT Lab																																		
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																																		
<b>Remark :</b>	5 camera install done working camer no A1,A2,4C,4B, DMLT Lab																																		
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>01-10-2025 05:14:41</td><td>MaroofRaza</td><td>Completed</td><td>5 camera install done working camer no A1,A2,4C,4B, DMLT Lab</td><td></td></tr><tr><td>01-10-2025 11:42:49</td><td>MaroofRaza</td><td>New</td><td></td><td>-</td></tr><tr><td>01-10-2025 11:39:54</td><td>MaroofRaza</td><td>New</td><td></td><td>-</td></tr><tr><td>30-09-2025 12:26:43</td><td>MaroofRaza</td><td>New</td><td></td><td>-</td></tr><tr><td>29-09-2025 12:25:54</td><td>MaroofRaza</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	01-10-2025 05:14:41	MaroofRaza	Completed	5 camera install done working camer no A1,A2,4C,4B, DMLT Lab		01-10-2025 11:42:49	MaroofRaza	New		-	01-10-2025 11:39:54	MaroofRaza	New		-	30-09-2025 12:26:43	MaroofRaza	New		-	29-09-2025 12:25:54	MaroofRaza	New		-
Date Time	Technician Name	Status	Remark	Sign																															
01-10-2025 05:14:41	MaroofRaza	Completed	5 camera install done working camer no A1,A2,4C,4B, DMLT Lab																																
01-10-2025 11:42:49	MaroofRaza	New		-																															
01-10-2025 11:39:54	MaroofRaza	New		-																															
30-09-2025 12:26:43	MaroofRaza	New		-																															
29-09-2025 12:25:54	MaroofRaza	New		-																															
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-11-2025 10:48:30</td><td>Neeraj Chauhan</td><td></td></tr><tr><td>07-10-2025 11:38:43</td><td>Atique Salmani</td><td>Shreeram school 20 25 camera add in primary nvr and 10 12 in secondry nvr and make list with ip And skilled area nvr one bullet camera cable was faulty but cable was too much ectre so cut and recrimping done but camera faulty and 2 dome camera faulty medical room skilled area. nvr 1.50 1.43 1.37 collect 3 cameras collect .</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-11-2025 10:48:30	Neeraj Chauhan		07-10-2025 11:38:43	Atique Salmani	Shreeram school 20 25 camera add in primary nvr and 10 12 in secondry nvr and make list with ip And skilled area nvr one bullet camera cable was faulty but cable was too much ectre so cut and recrimping done but camera faulty and 2 dome camera faulty medical room skilled area. nvr 1.50 1.43 1.37 collect 3 cameras collect .																					
Date Time	Technician Name	Remark																																	
19-11-2025 10:48:30	Neeraj Chauhan																																		
07-10-2025 11:38:43	Atique Salmani	Shreeram school 20 25 camera add in primary nvr and 10 12 in secondry nvr and make list with ip And skilled area nvr one bullet camera cable was faulty but cable was too much ectre so cut and recrimping done but camera faulty and 2 dome camera faulty medical room skilled area. nvr 1.50 1.43 1.37 collect 3 cameras collect .																																	