Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status D	etails • VF15/62						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9820858158						
Technician Name :	Ravi Rajbhar			Technician Mobile :	8080922965	8080922965	
Ticket Type:	Complain	Da	ite & Time :	02-08-2025 10:27	:07		
Vendor Details :		•					
Company Name/Client Name :	Vedantaa Institute Academic(Shrenik		stomer's obile :	9820858158	Name:	Dipesh Sir	
Address:				-			
Mumbai , , , , M	aharashtra						
AMC Details:							
Expiry Date :	01-01-1970 05:30:00			Type:			
Product Name:	Access						
Complain:	1)turnstile lock nee showing 4)Ground			rror issue 3)2 user r to get lock	new added but pho	oto not	
Technician Comment :	1st floor one turnstile lock install against faulty and faulty divice handover to client And ground floor software issue resolved but under observation And one turnstile limit switch issue need to change next time						
Complain Operator :	Desktop - Apurva Vajaria						
Remark :				y and faulty divice h ation And one turns			
Status History :	Date Time	Technicia Name	n Status	Ren	nark	Sign	
	02-08-2025 04:04:03	Ravi Rajbha	r Completed	1st floor one turnst against faulty and f handover to client A software issue reso observation And on switch issue need to	aulty divice And ground floor Ived but under e turnstile limit	Pais	
	02-08-2025 04:04:03	Ravi Rajbha	r Completed	1st floor one turnst against faulty and f handover to client A software issue reso observation And on switch issue need to	aulty divice And ground floor lved but under e turnstile limit	(Adis	
	02-08-2025 10:27:13	Ravi Rajbha	r New			-	

Previous Complain History :	Date Time	Technician Name	Remark	
ilistory.	06-08-2025 10:30:14	Ravi Rajbhar	1st floor one divice issue resolved and ok working done with cable change And one rj 45 four pin connector install And ground floor limit switch install and ok working done But ground floor web software uninstall bcz Sql sarver not responding inform to Yogesh sir It team told Pc format tomorrow then install software inform to shreink sir also	
	18-06-2025 10:38:20	Ravi Rajbhar	First floor 1)one turnstile it is getting stuck issue resolved and ok working done 2)one turnstile in out both magnetic lock issue and both lock remove and take to office 3)biomax web software licence key update done Ground floor orbit mess 1)Biometric adapter change and faulty handover to client 2)1 turnstile magnetic lock change against faulty 3)4 Pin lan cable change all ok working done work completed	