## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Details : VE430								
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	9702172944							
Technician Name :	Zainul Shaikh		Technician Mobile	8080922971				
Ticket Type :	Complain	Date & Time:	25-09-2019 10:43:15					
Vendor Details :								
Company Name/Client Name :	Concentrix Daksh Services India Pvt Ltd - Andheri	Customer's Mobile :	9702172944	Name :	Ganesh Sir			
Address:								
Mumbai , , , 400	0057 , Maharashtra							
AMC Details:				_				
Expiry Date :	01-01-1970 05:30:00		Type:					
Product Name :	CCTV							
Complain:	190924001 - Camera no#10 from DVR 3 need to be adjust. 190924002 - Camera no#1 from DVR 1 is showing blur images and camera no#13 from DVR 1 is showing video loss. 190924003 - DVR#1 & DVR#2 are showing HDD doesn't exist (issue in overwrite)							
Technician Comment :	9th flr server room and 8th flr reception camera blur issue solved now working ok. 8th flr HDFC camera issue solved now working ok. 4 channel dvr power supply changed now HDD issue solved . online DVR 5 4tb HDD faulty need to change. 8th flr reception door Buzzer installation done now working ok. HDFC door buzzer pending bcs they require small one buzzer.							
Complain Operator :	Desktop - Apurva Vajaria							
Remark:	9th flr server room and 8th flr reception camera blur issue solved now working ok. 8th flr HDFC camera issue solved now working ok. 4 channel dvr power supply changed now HDD issue solved . online DVR 5 4th HDD faulty need to change. 8th flr reception door Buzzer installation done now working ok. HDFC door buzzer pending bcs they require small one buzzer.							

Status History :	Date Time	Technician Name	Status	Remark	Sign	
	25-09-2019 03:47:29	ZainulShaikh	Completed	9th flr server room and 8th flr reception camera blur issue solved now working ok. 8th flr HDFC camera issue solved now working ok. 4 channel dvr power supply changed now HDD issue solved . online DVR 5 4tb HDD faulty need to change. 8th flr reception door Buzzer installation done now working ok. HDFC door buzzer pending bcs they require small one buzzer.	Zoir	
	25-09-2019 10:43:20	ZainulShaikh	New		-	
	25-09-2019 10:43:16	ZainulShaikh	New		-	
Previous Complain History :	Date Time	Technician Nan	ne	Remark		
	30-10-2019 11:14:08 Atique Salmani			5cameras issue resolved 4aftr changed smps and one v distributer reconction.		
	18-10-2019 12:37:39					

l