




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE5535																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	8796230983																													
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																										
Ticket Type :	Complain	Date & Time :	24-05-2022 10:18:43																											
Vendor Details :																														
Company Name/Client Name :	Secure Debt Management Consultants Llp	Customer's Mobile :	8796230983	Name :	Gaurav Kulkarni																									
Address :																														
Mumbai , , , 400031 , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	Ppm																													
Complain :	WLD																													
Technician Comment :	check water leak detector panel all connections ok and also check by water dropping on zone iys hootring system healthy.																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	check water leak detector panel all connections ok and also check by water dropping on zone iys hootring system healthy.																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-05-2022 04:07:32</td><td>Atique Salmani</td><td>Closed</td><td></td><td>-</td></tr><tr><td>24-05-2022 10:58:21</td><td>Atique Salmani</td><td>Completed</td><td>check water leak detector panel all connections ok and also check by water dropping on zone iys hootring system healthy.</td><td></td></tr><tr><td>24-05-2022 10:18:57</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>24-05-2022 10:18:43</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-05-2022 04:07:32	Atique Salmani	Closed		-	24-05-2022 10:58:21	Atique Salmani	Completed	check water leak detector panel all connections ok and also check by water dropping on zone iys hootring system healthy.		24-05-2022 10:18:57	Atique Salmani	New		-	24-05-2022 10:18:43	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
25-05-2022 04:07:32	Atique Salmani	Closed		-																										
24-05-2022 10:58:21	Atique Salmani	Completed	check water leak detector panel all connections ok and also check by water dropping on zone iys hootring system healthy.																											
24-05-2022 10:18:57	Atique Salmani	New		-																										
24-05-2022 10:18:43	Atique Salmani	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>15-04-2022 11:52:10</td><td>Atique Salmani</td><td>check wld system zone healthy it's working ok use SMPS for hooter becз pannel 12 volt output not giving so use saprate SMPS .</td></tr><tr><td>09-12-2020 10:46:16</td><td>Atique Salmani</td><td>2 zone WLD pannel installed with cable laying in Server and also tested ok zone one.</td></tr></tbody></table>					Date Time	Technician Name	Remark	15-04-2022 11:52:10	Atique Salmani	check wld system zone healthy it's working ok use SMPS for hooter becз pannel 12 volt output not giving so use saprate SMPS .	09-12-2020 10:46:16	Atique Salmani	2 zone WLD pannel installed with cable laying in Server and also tested ok zone one.																
Date Time	Technician Name	Remark																												
15-04-2022 11:52:10	Atique Salmani	check wld system zone healthy it's working ok use SMPS for hooter becз pannel 12 volt output not giving so use saprate SMPS .																												
09-12-2020 10:46:16	Atique Salmani	2 zone WLD pannel installed with cable laying in Server and also tested ok zone one.																												