Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE10648 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 0235034308 **No. :** Technician Ravi Rajbhar **Technician Mobile** 8080922965 Name : : **Ticket Type :** Complain Date & Time : 27-01-2024 12:46:23 Vendor Details : Customer's Ghanshayam Tower Company Ventura Alloy 0235034308 Name : Name/Client Kandivali Site Mobile : Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV many cameras showing no link issue **Complain**: intercom issue pending reception 100 number and outgoing incoming Technician **Comment** : Complain Desktop - Apurva Vajaria **Operator** : intercom issue pending reception 100 number and outgoing incoming Gulam bhai visited the site **Remark** : and issue resolved

Status History :	Date Time	Technician	Status	Remark	Sign
		Name			- 3
	22-02-2024 03:40:35	Ravi Rajbhar	Closed		-
	21-02-2024 01:14:37	Ravi Rajbhar	Completed		-
	30-01-2024 11:34:15	Ravi Rajbhar	Work Pending	intercom issue pending reception 100 number and outgoing incoming	J & Mr
	30-01-2024 10:25:00	Ravi Rajbhar	New		-
	29-01-2024 01:59:43	Ravi Rajbhar	New		-
	29-01-2024 12:54:38	Ravi Rajbhar	Work Pending	Reception phone not working so we checked cable there is issue in one pair so use another pair but there is some issue in port need to recheck so it's painding and cctv kandiwali office all working only bhiwandi cameras offline becz static IP is expired.ppm also painding.	bughal
	29-01-2024 11:05:04	Ravi Rajbhar	New		-
Previous Complain History :	Date Time	Technician Name	Remark		
	10-02-2024 12:02:39	Atique Salmani	Ppm done all system cctv fire access epbax working ok only godown NVR hdmi cable damge so viewing painding need to 3 metr cable changed after approval.		
	05-02-2024 01:09:17	Ravi Rajbhar	one ex.no.change with switch ex.no.101 and 105 with cable puching in system refer ticket no. VE10650		