




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15107																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	0235034308																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	25-06-2025 01:47:45																	
Vendor Details :																				
Company Name/Client Name :	Ventura Alloy Kandivali 12th Floor Office	Customer's Mobile :	0235034308	Name :	Ghanshayam Tower															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	1)Router changed bhiwandi biometric offline issue 2)Extension no. 106 not working																			
Technician Comment :	One extension no. 106 line ok instrument 4 pin connector missing client side need to change then issue resolve																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	One extension no. 106 line ok instrument 4 pin connector missing client side need to change then issue resolve																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-06-2025 06:11:23</td><td>Ravi Rajbhar</td><td>Completed</td><td>One extension no. 106 line ok instrument 4 pin connector missing client side need to change then issue resolve</td><td></td></tr><tr><td>25-06-2025 01:47:50</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-06-2025 06:11:23	Ravi Rajbhar	Completed	One extension no. 106 line ok instrument 4 pin connector missing client side need to change then issue resolve		25-06-2025 01:47:50	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
25-06-2025 06:11:23	Ravi Rajbhar	Completed	One extension no. 106 line ok instrument 4 pin connector missing client side need to change then issue resolve																	
25-06-2025 01:47:50	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-06-2025 11:00:38</td><td>Ravi Rajbhar</td><td>Biometric attendance software and epxax system issue resolved and ok working done</td></tr><tr><td>04-06-2025 01:46:01</td><td>Ravi Rajbhar</td><td>One line extension no. 101 . issue resolved and ok working done</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-06-2025 11:00:38	Ravi Rajbhar	Biometric attendance software and epxax system issue resolved and ok working done	04-06-2025 01:46:01	Ravi Rajbhar	One line extension no. 101 . issue resolved and ok working done						
Date Time	Technician Name	Remark																		
14-06-2025 11:00:38	Ravi Rajbhar	Biometric attendance software and epxax system issue resolved and ok working done																		
04-06-2025 01:46:01	Ravi Rajbhar	One line extension no. 101 . issue resolved and ok working done																		