







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15624																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	0235034308																													
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																										
Ticket Type :	Complain	Date & Time :	23-08-2025 10:37:08																											
Vendor Details :																														
Company Name/Client Name :	Ventura Alloy Kandivali 12th Floor Office	Customer's Mobile :	0235034308	Name :	Ghanshayam Tower																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	01-01-1970 05:30:00		Type :																											
Product Name :	CCTV																													
Complain :	tv is also changed then too cameras issues of viewing is not solved..																													
Technician Comment :	Tv issue resolved and 13th floor nvr required oprate by mouse so need cabling 15 20 metr off possible and mouse extender 1 nos and existing mouse extender need to changed .																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	Tv issue resolved and 13th floor nvr required oprate by mouse so need cabling 15 20 metr off possible and mouse extender 1 nos and existing mouse extender need to changed .																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-08-2025 11:05:38</td><td>Atique Salmani</td><td>Completed</td><td>Tv issue resolved and 13th floor nvr required oprate by mouse so need cabling 15 20 metr off possible and mouse extender 1 nos and existing mouse extender need to changed .</td><td></td></tr><tr><td>25-08-2025 11:05:38</td><td>Atique Salmani</td><td>Completed</td><td>Tv issue resolved and 13th floor nvr required oprate by mouse so need cabling 15 20 metr off possible and mouse extender 1 nos and existing mouse extender need to changed .</td><td></td></tr><tr><td>25-08-2025 10:09:04</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>23-08-2025 10:37:31</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-08-2025 11:05:38	Atique Salmani	Completed	Tv issue resolved and 13th floor nvr required oprate by mouse so need cabling 15 20 metr off possible and mouse extender 1 nos and existing mouse extender need to changed .		25-08-2025 11:05:38	Atique Salmani	Completed	Tv issue resolved and 13th floor nvr required oprate by mouse so need cabling 15 20 metr off possible and mouse extender 1 nos and existing mouse extender need to changed .		25-08-2025 10:09:04	Atique Salmani	New		-	23-08-2025 10:37:31	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
25-08-2025 11:05:38	Atique Salmani	Completed	Tv issue resolved and 13th floor nvr required oprate by mouse so need cabling 15 20 metr off possible and mouse extender 1 nos and existing mouse extender need to changed .																											
25-08-2025 11:05:38	Atique Salmani	Completed	Tv issue resolved and 13th floor nvr required oprate by mouse so need cabling 15 20 metr off possible and mouse extender 1 nos and existing mouse extender need to changed .																											
25-08-2025 10:09:04	Atique Salmani	New		-																										
23-08-2025 10:37:31	Atique Salmani	New		-																										

Previous Complain History :	Date Time	Technician Name	Remark
	25-06-2025 01:47:45	Ravi Rajbhar	One extension no. 106 line ok instrument 4 pin connector missing client side need to change then issue resolve
	14-06-2025 11:00:38	Ravi Rajbhar	Biometric attendance software and epbax system issue resolved and ok working done