







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15803																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	0235034308																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	16-09-2025 10:47:04																						
Vendor Details :																									
Company Name/Client Name :	Ventura Alloy Kandivali 12th Floor Office	Customer's Mobile :	0235034308	Name :	Ghanshayam Tower																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Fire																								
Complain :	Fire one zone open issue																								
Technician Comment :	Fire zone open issue resolved all detector chek and issue resolved working ok boathe zone panel helthy																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	Fire zone open issue resolved all detector chek and issue resolved working ok boathe zone panel helthy																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>16-09-2025 11:45:10</td><td>Atique Salmani</td><td>Completed</td><td>Fire zone open issue resolved all detector chek and issue resolved working ok boathe zone panel helthy</td><td></td></tr><tr><td>16-09-2025 11:45:10</td><td>Atique Salmani</td><td>Completed</td><td>Fire zone open issue resolved all detector chek and issue resolved working ok boathe zone panel helthy</td><td></td></tr><tr><td>16-09-2025 10:47:11</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	16-09-2025 11:45:10	Atique Salmani	Completed	Fire zone open issue resolved all detector chek and issue resolved working ok boathe zone panel helthy		16-09-2025 11:45:10	Atique Salmani	Completed	Fire zone open issue resolved all detector chek and issue resolved working ok boathe zone panel helthy		16-09-2025 10:47:11	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
16-09-2025 11:45:10	Atique Salmani	Completed	Fire zone open issue resolved all detector chek and issue resolved working ok boathe zone panel helthy																						
16-09-2025 11:45:10	Atique Salmani	Completed	Fire zone open issue resolved all detector chek and issue resolved working ok boathe zone panel helthy																						
16-09-2025 10:47:11	Atique Salmani	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-09-2025 10:38:09</td><td>TauseephRaza</td><td>Acces issue done fire issue</td></tr><tr><td>23-08-2025 10:37:08</td><td>Atique Salmani</td><td>Tv issue resolved and 13th floor nvr required oprate by mouse so need cabling 15 20 metr off possible and mouse extender 1 nos and existing mouse extender need to changed .</td></tr></tbody></table>					Date Time	Technician Name	Remark	13-09-2025 10:38:09	TauseephRaza	Acces issue done fire issue	23-08-2025 10:37:08	Atique Salmani	Tv issue resolved and 13th floor nvr required oprate by mouse so need cabling 15 20 metr off possible and mouse extender 1 nos and existing mouse extender need to changed .											
Date Time	Technician Name	Remark																							
13-09-2025 10:38:09	TauseephRaza	Acces issue done fire issue																							
23-08-2025 10:37:08	Atique Salmani	Tv issue resolved and 13th floor nvr required oprate by mouse so need cabling 15 20 metr off possible and mouse extender 1 nos and existing mouse extender need to changed .																							