Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : $| \mathbf{W} :$ www.vallabhenterprises.com $\mathbf{E} :$ vallabhsecure@yahoo.co.in

Service Status Deta	ils : VE388						
Priority :	Low						
Created By :	Admin - Apurva Vajaria						
Complaint Mob. No. :	0235034308						
Technician Name :	Sachin Pawar			Fechnician Mobile :	808092298	8080922981	
Ticket Type :	Complain Date & Time		e:	20-09-2019 01:14:59			
Vendor Details :							
Company Name/Client Name :	Ventura Alloy Kandivali Site Customer's Mobile :			0235034308	Name :	Ghanshayam Tower	
Address :							
Mumbai , , , , Maharashtra							
AMC Details :							
Expiry Date :	01-01-1970 05:30:00			Type :			
Product Name :	Access						
Complain :	door lock issue						
Technician Comment :							
Complain Operator :	Desktop - Apurva Vajaria						
Remark :	mode was on fire as fire alarm was getting activated due to smoke sensor installed above temple covered sensor with tape as per clients confirmation						
Status History :	Date Time 03-10-2019 01:31:39 23-09-2019 01:10:17 23-09-2019 11:26:56 20-09-2019 01:15:04 20-09-2019 01:15:00		Technician Name		Status	Remark	Sign
			SachinPawar		Completed		-
			SachinPawar		New		-
			SachinPawar		Completed		-
			SachinPawar		New		-
			SachinPawar		New		-
Previous Complain History :	Date Time	Technicia	an Name	Remark			
	24-07-2023 11:54:28	Ravi Raji	ohar	ppm done of cctv system , fire panal , epbax systam and access all ok working done and TA softwere check network issue client side			
	22-07-2023 10:23:12	Atique Sa	almani	Check recording total 15 days but 1 to 20 not record from 21 to 22 available only keep hdd on overwrite and also formated hdd after permission Deepika ma and keep on under observation.			