




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE1140																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	8451099978																								
Technician Name :	Zainul Shaikh		Technician Mobile :	8080922971																					
Ticket Type :	Complain	Date & Time :	14-02-2020 09:58:15																						
Vendor Details :																									
Company Name/Client Name :	Dev Research Centre	Customer's Mobile :	8451099978	Name :	Hitesh Doshi																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	06-06-2021 12:00:00		Type :	Comprehensive																					
Product Name :	Fire																								
Complain :	fire alarm issue																								
Technician Comment :	main supply plug in direction change. resistor connect in panel side. now under observation																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	main supply plug in direction change. resistor connect in panel side. now under observation																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>14-02-2020 05:34:31</td><td>ZainulShaikh</td><td>Completed</td><td>main supply plug in direction change. resistor connect in panel side. now under observation</td><td></td></tr><tr><td>14-02-2020 10:12:01</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr><tr><td>14-02-2020 09:58:16</td><td>ZainulShaikh</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	14-02-2020 05:34:31	ZainulShaikh	Completed	main supply plug in direction change. resistor connect in panel side. now under observation		14-02-2020 10:12:01	ZainulShaikh	New		-	14-02-2020 09:58:16	ZainulShaikh	New		-
Date Time	Technician Name	Status	Remark	Sign																					
14-02-2020 05:34:31	ZainulShaikh	Completed	main supply plug in direction change. resistor connect in panel side. now under observation																						
14-02-2020 10:12:01	ZainulShaikh	New		-																					
14-02-2020 09:58:16	ZainulShaikh	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-07-2023 11:06:26</td><td>Sonu Kumar</td><td>Security cabin fire panal install and 3rd floor MCB light on issue resolved working ok</td></tr><tr><td>03-07-2023 10:44:14</td><td>Kalpesh SubhashGurav</td><td>All Extention Check Done. 110,106,111, Problem Solved Security Gate Ext.100 Problem Solved.</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-07-2023 11:06:26	Sonu Kumar	Security cabin fire panal install and 3rd floor MCB light on issue resolved working ok	03-07-2023 10:44:14	Kalpesh SubhashGurav	All Extention Check Done. 110,106,111, Problem Solved Security Gate Ext.100 Problem Solved.											
Date Time	Technician Name	Remark																							
14-07-2023 11:06:26	Sonu Kumar	Security cabin fire panal install and 3rd floor MCB light on issue resolved working ok																							
03-07-2023 10:44:14	Kalpesh SubhashGurav	All Extention Check Done. 110,106,111, Problem Solved Security Gate Ext.100 Problem Solved.																							