## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Details : VE3336									
Priority:	Low								
Created By:	Admin - Apurva Vajaria								
Complaint Mob. No. :	8451099978								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984					
Ticket Type :	Complain	Date & Time :	30-06-2021 12:37:37						
Vendor Details :									
Company Name/Client Name :	Dev Research Centre	Customer's Mobile :	8451099978	Name :	Hitesh Doshi				
Address:									
Mumbai , , , , M	aharashtra								
AMC Details:	_		_	_					
Expiry Date :	06-06-2021 12:00:00		Type:	Comprehensive					
Product Name:	Ppm								
Complain:	Access / fire / epabx								
Technician Comment :	extaintion nmbr 114 not working so check the cable continuti and use another pair line working ok and 113 line ok instrument issue and check all floor fire by MCP and rest from MCP and fire panel also all door releasing when fire clean all S.D.and. also clean main gate fire pannel and amoke detector boath pannel working healthy condition .all door acces working ok check all door by our user and password . main gate security cabin fire pannel battery rushted .								
Complain Operator :	Desktop - Apurva Vajaria								
Remark :	extaintion nmbr 114 not working so check the cable continuti and use another pair line working ok and 113 line ok instrument issue and check all floor fire by MCP and rest from MCP and fire panel also all door releasing when fire clean all S.D.and. also clean main gate fire pannel and amoke detector boath pannel working healthy condition .all door access working ok check all door by our user and password . main gate security cabin fire pannel battery rushted .								

Status History :	Date Time	Technician Name	Status	Remark	Sign
	30-06-2021 02:15:12	Atique Salmani	Completed	extaintion nmbr 114 not working so check the cable continuti and use another pair line working ok and 113 line ok instrument issue and check all floor fire by MCP and rest from MCP and fire panel also all door releasing when fire clean all S.D.and. also clean main gate fire pannel and amoke detector boath pannel working healthy condition .all door acces working ok check all door by our user and password . main gate security cabin fire pannel battery rushted .	Man
	30-06-2021 12:37:52	Atique Salmani	New		-
	30-06-2021 12:37:38	Atique Salmani	New		-
Previous Complain History:	Date Time Technician		n Name	e Remark	
	14-07-2023 11:06:26 Sonu Kumar		Security cabin fire panal install and 3rd floor MCB light issue resolved working ok		MCB light on
	03-07-2023 10:44:14 Kalpesh St		hashGurav	rav All Extention Check Done. 110,106,111, Problem Solved Security Gate Ext.100 Problem Solved.	