Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE4117 Low **Priority** : **Created By :** Admin - Apurva Vajaria Complaint 8451099978 Mob. No. : Technician Atique Salmani **Technician Mobile :** 8080922984 Name : Complain 26-10-2021 10:50:43 **Ticket Type : Date & Time : Vendor Details :** Dev Research Customer's Mobile : 8451099978 Hitesh Doshi Company Name : Name/Client Centre Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 06-06-2021 12:00:00 Comprehensive Expiry Date : Type : **Product Name :** Ppm Access/EPABX/Fire **Complain**: All sd clean and check fire Alarm panel working ok all zones normal gr. To 3rd floor and security **Technician** cabin 2 base and sd faulty need to changed .one is fully rushted and second is not forword suply **Comment** : to next s.d.sonits painding.ppm done all . also check epbax system 108 female soct fulty line ok. Complain Desktop - Apurva Vajaria **Operator** : All sd clean and check fire Alarm panel working ok all zones normal gr. To 3rd floor and security **Remark** : cabin 2 base and sd faulty need to changed .one is fully rushted and second is not forword suply to next s.d.sonits painding.ppm done all . also check epbax system 108 female soct fulty line ok. **Status History :** Technician **Date Time** Status Remark Sign Name 26-10-2021 Atique Salmani Completed All sd clean and check fire Alarm 04:36:07 panel working ok all zones normal gr. To 3rd floor and security cabin 2 base and sd faulty need to changed .one is fully rushted and second is not forword suply to next s.d.sonits painding.ppm done all . also check epbax system 108 female soct fulty line ok. 26-10-2021 Atique Salmani New 10:51:12 26-10-2021 Atique Salmani New 10:50:43

Previous Complain History :	Date Time	Technician Name	Remark
	04-02-2022 10:29:01	Siddhesh Chavan	PPM work of Acess , Fire, Epbax done All smoke detector cleaned . and also all door acces checked MCP , hooter fire test done. intercom system working ok all line working ok. 2) 1 st floor biomatric machines take to office for checking and finger sensor not working
	08-12-2021 10:37:26	Neeraj Chauhan	Port setting in device done Software port chenges Software on static ip done device IP issues solve.