Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status Det	ails: VE5613					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob. No. :	8451099978					
Technician Name:	Atique Salmani		Technician Mobile : 8080922984			
Ticket Type :	Complain	Date & Time :	01-06-2022 10:04:15			
Vendor Details :						
Company Name/Client Name :	Dev Research Centre	Customer's Mobile :	8451099978		Name :	Hitesh Doshi
Address :						
Mumbai , , , , Mah	arashtra					
AMC Details :						
Expiry Date :	06-06-2021 12:00:	00	Type:		Comprehensive	
Product Name:	Access					
Complain :	lock issue					
Technician Comment :	2 old e.m. lock remooved and reinstalled on metal door and one employee finger add.work completed.					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	2 old e.m. lock remooved and reinstalled on metal door and one employee finger add.work completed.					
Status History :	Date Time	Technician Name	Status	Remark		Sign
	03-06-2022 05:17:48	Atique Salmani	Closed			-
	01-06-2022 02:05:55	Atique Salmani	Completed	2 old e.m. lock remooved and reinstalled on metal door and one employee finger add.work completed.		B/5/22
	01-06-2022 10:10:13	Atique Salmani	New			-
	01-06-2022 10:04:15	Atique Salmani	New			-
Previous Complain History :	Date Time	Technician Name	Remark			
	26-05-2022 10:51:15	MayurYadav	heat detector check, clean and swipe security cabin hooter connect only in security cabin fire panel not integrate with main building fire panel			
	23-05-2022 10:13:06	Siddhesh Chavan	all access working okay biometric working okay epbx system working OK all line working fire first zone open issue resolve and all smoke detector clean and all hooters working OK and 2 panel working okay			