## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE8846 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 8451099978 **No. :** Technician Sonu Kumar **Technician Mobile :** 8454016444 Name : Complain 14-07-2023 11:06:26 **Ticket Type : Date & Time :** Vendor Details : Company Dev Research Customer's Mobile 8451099978 Hitesh Doshi Name : Name/Client Centre Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 06-06-2021 12:00:00 Comprehensive Expiry Date : Type : **Product Name :** Fire **Complain**: fire alram low battery fault issue Security cabin fire panal install and 3rd floor MCB light on issue resolved working ok Technician **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : Security cabin fire panal install and 3rd floor MCB light on issue resolved working ok **Status History :** Technician **Date Time** Status Remark Sign Name 21-07-2023 Sonu Kumar Completed Security cabin fire panal install and 3rd floor MCB 03:06:54 light on issue resolved working ok 21-07-2023 Sonu Kumar New 10:34:08 main gate watchman cabin 14-07-2023 Sonu Kumar Work Pending M 11:19:01 fire panal check but fire main bord charching point faulty then remove main bord with collacat to office canfirm to apurva sir 14-07-2023 Sonu Kumar New 11:06:35

Previous Complain History :	Date Time	Technician Name	Remark
	31-08-2023 10:28:49	Atique Salmani	All floor smoke detectors clean and all floor door access checked and intercom also checked there is instrument issue 113/109/dvr rrom 2nd floor one cabin and checked by mcp press all floor hootring and ground floor security cabin fire hooter and battery issue so collect and set date and time in biomatric devices .ppm work completed hooter n battery painding security cabin main gate .
	11-08-2023 12:04:04	DilshadKhan	1st foolr door access devise machine installed after repair working ok.