


# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE9341</b>					
<b>Priority :</b>	Low				
<b>Created By :</b>	Admin - Apurva Vajaria				
<b>Complaint Mob. No. :</b>	8451099978				
<b>Technician Name :</b>	Munna Gupta		<b>Technician Mobile :</b>	8080922982	
<b>Ticket Type :</b>	AMC visiting	<b>Date &amp; Time :</b>	31-08-2023 10:28:49		
<b>Vendor Details :</b>					
<b>Company Name/Client Name :</b>	Dev Research Centre	<b>Customer's Mobile :</b>	8451099978	<b>Name :</b>	Hitesh Doshi
<b>Address :</b>					
Mumbai , , , , Maharashtra					
<b>AMC Details :</b>					
<b>Expiry Date :</b>	06-06-2021 12:00:00		<b>Type :</b>	Comprehensive	
<b>Product Name :</b>	Ppm				
<b>Complain :</b>	Access / EPABX / Fire PPM need to do				
<b>Technician Comment :</b>	All floor smoke detectors clean and all floor door access checked and intercom also checked there is instrument issue 113/109/dvr rrom 2nd floor one cabin and checked by mcp press all floor hootring and ground floor security cabin fire hooter and battery issue so collect and set date and time in biometric devices .ppm work completed hooter n battery painding security cabin main gate .				
<b>Complain Operator :</b>	Desktop - Apurva Vajaria				
<b>Remark :</b>	All floor smoke detectors clean and all floor door access checked and intercom also checked there is instrument issue 113/109/dvr rrom 2nd floor one cabin and checked by mcp press all floor hootring and ground floor security cabin fire hooter and battery issue so collect and set date and time in biometric devices .ppm work completed hooter n battery painding security cabin main gate .				

Status History :	Date Time	Technician Name	Status	Remark	Sign
	08-09-2023 10:47:37	Munna Gupta	New		-
	01-09-2023 04:19:11	Munna Gupta	Work Pending		-
	31-08-2023 02:39:51	Munna Gupta	Completed	All floor smoke detectors clean and all floor door access checked and intercom also checked there is instrument issue 113/109/dvr rrom 2nd floor one cabin and checked by mcp press all floor hootring and ground floor security cabin fire hooter and battery issue so collect and set date and time in biometric devices .ppm work completed hooter n battery painding security cabin main gate .	
	31-08-2023 10:29:28	Munna Gupta	New		-
Previous Complain History :	Date Time	Technician Name	Remark		
	12-09-2023 11:25:36	Ravi Rajbhar	all ex. number check allready ok working done all ex.no. and only password change Admin@123 ip 192.168.1.101		
	11-08-2023 12:04:04	DilshadKhan	1st foolr door access devise machine installed after repair working ok.		