




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE6980</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9769948909																								
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	30-11-2022 02:55:47																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Umiya Developers	Customer's Mobile :	9769948909	Name :	Hitesh Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	Gate camera off issue																								
<b>Technician Comment :</b>	main gate camera working ok																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	main gate camera working ok																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>30-11-2022 05:33:07</td><td>Siddhesh Chavan</td><td>Completed</td><td>main gate camera working ok</td><td></td></tr><tr><td>30-11-2022 04:04:27</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>30-11-2022 02:56:06</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	30-11-2022 05:33:07	Siddhesh Chavan	Completed	main gate camera working ok		30-11-2022 04:04:27	Siddhesh Chavan	New		-	30-11-2022 02:56:06	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																					
30-11-2022 05:33:07	Siddhesh Chavan	Completed	main gate camera working ok																						
30-11-2022 04:04:27	Siddhesh Chavan	New		-																					
30-11-2022 02:56:06	Siddhesh Chavan	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-11-2022 11:49:20</td><td>Ravi Rajbhar</td><td>one op ptz camera no video issue resolved and ok working done and two camera cable faulty back side camera/ a wing b wing main intercne one 4 port poe switch install and faulty remove and take to office 2 pair video blun change two camera cable aprox 250_300 mter</td></tr><tr><td>16-11-2022 10:21:53</td><td>Sonu Kumar</td><td>2 camera issue resolved working ok and one camera blur issue resolved working ok and one camera shifting pending cable joint 100 MTR and dvr to camera 180 MTR cable</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-11-2022 11:49:20	Ravi Rajbhar	one op ptz camera no video issue resolved and ok working done and two camera cable faulty back side camera/ a wing b wing main intercne one 4 port poe switch install and faulty remove and take to office 2 pair video blun change two camera cable aprox 250_300 mter	16-11-2022 10:21:53	Sonu Kumar	2 camera issue resolved working ok and one camera blur issue resolved working ok and one camera shifting pending cable joint 100 MTR and dvr to camera 180 MTR cable											
Date Time	Technician Name	Remark																							
19-11-2022 11:49:20	Ravi Rajbhar	one op ptz camera no video issue resolved and ok working done and two camera cable faulty back side camera/ a wing b wing main intercne one 4 port poe switch install and faulty remove and take to office 2 pair video blun change two camera cable aprox 250_300 mter																							
16-11-2022 10:21:53	Sonu Kumar	2 camera issue resolved working ok and one camera blur issue resolved working ok and one camera shifting pending cable joint 100 MTR and dvr to camera 180 MTR cable																							