Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE12151 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9322637846 **No. : Technician Technician Mobile** 7489567735 Shiva Meena Name : New Installation Date & Time : 15-07-2024 03:32:31 **Ticket Type : Vendor Details :** Company Deepak Shah Customer's Mobile 9322637846 Indibrand Name : Name/Client Solutions Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV 2 cameras additional and biometric device need to install **Complain**: Cebaling work complete and 2 camera canecsan done work complete and bayomex mashin usr Technician add done work complete **Comment**: Complain Desktop - Apurva Vajaria **Operator** : **Remark** : Cebaling work complete and 2 camera canecsan done work complete and bayomex mashin usr add done work complete **Status History :** Technician **Date Time** Status Remark Sign Name 18-07-2024 Completed Cebaling work complete and 2 Shiva Meena 02:08:07 camera canecsan done work complete and bayomex mashin usr add done work complete 18-07-2024 Shiva Meena New 11:43:25 16-07-2024 Shiva Meena Client Side Ravel panel and Siemens smoke 11:51:44 detectors There is no cat 6 cable from fire pannel to lock SMPS junction need to cabling after that it will be possible so it's painding. 15-07-2024 Shiva Meena In Progress Biomatric installation done software and facefi ger adding 07:22:14painding camera cable laying half cabling painding . 15-07-2024 Shiva Meena New 03:32:37

Previous Complain History :	Date Time	Technician Name	Remark
	15-06-2024 12:04:12	MayurYadav	Mobile account change Camera mic off username indibrand sales@indibrandsolution.co.in Online in Deepak sir system
	10-06-2024 05:52:07	Neeraj Chauhan	Network change and nvr reconfigure and nvr side dressing done 2 camera issues solve and all call ip camera and add on nvr laptop ivms camera not import issue