




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE2052</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9820606496																								
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	19-10-2020 01:25:53																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Skylone	<b>Customer's Mobile :</b>	9820606496	<b>Name :</b>	Irani Wadi																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	VDP																								
<b>Complain :</b>	b504 CANNOT VIEW LOBBY PANEL																								
<b>Technician Comment :</b>	B Wing 504 recrimping done from duct side and readd from lobby panel and also told to flate owener How to oprate and visit 2204 B Wing client say for next visit. so..																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	B Wing 504 recrimping done from duct side and readd from lobby panel and also told to flate owener How to oprate and visit 2204 B Wing client say for next visit. so..																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>19-10-2020 03:12:45</td><td>Atique Salmani</td><td>Completed</td><td>B Wing 504 recrimping done from duct side and readd from lobby panel and also told to flate owener How to oprate and visit 2204 B Wing client say for next visit. so..</td><td></td></tr><tr><td>19-10-2020 01:26:11</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>19-10-2020 01:25:54</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	19-10-2020 03:12:45	Atique Salmani	Completed	B Wing 504 recrimping done from duct side and readd from lobby panel and also told to flate owener How to oprate and visit 2204 B Wing client say for next visit. so..		19-10-2020 01:26:11	Atique Salmani	New		-	19-10-2020 01:25:54	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
19-10-2020 03:12:45	Atique Salmani	Completed	B Wing 504 recrimping done from duct side and readd from lobby panel and also told to flate owener How to oprate and visit 2204 B Wing client say for next visit. so..																						
19-10-2020 01:26:11	Atique Salmani	New		-																					
19-10-2020 01:25:54	Atique Salmani	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>23-10-2020 11:36:12</td><td>Atique Salmani</td><td>801 camera installed and working ok 802 remmooved and installed in 1001 and 903 /904 not vewing lobby issue resolved. and also b wing 2204 issue resolved.</td></tr><tr><td>13-10-2020 10:08:52</td><td>Neeraj Chauhan</td><td>c wing 2 camera install b wing 2 camera install total 4 cameras install all camera working okk</td></tr></tbody></table>					Date Time	Technician Name	Remark	23-10-2020 11:36:12	Atique Salmani	801 camera installed and working ok 802 remmooved and installed in 1001 and 903 /904 not vewing lobby issue resolved. and also b wing 2204 issue resolved.	13-10-2020 10:08:52	Neeraj Chauhan	c wing 2 camera install b wing 2 camera install total 4 cameras install all camera working okk											
Date Time	Technician Name	Remark																							
23-10-2020 11:36:12	Atique Salmani	801 camera installed and working ok 802 remmooved and installed in 1001 and 903 /904 not vewing lobby issue resolved. and also b wing 2204 issue resolved.																							
13-10-2020 10:08:52	Neeraj Chauhan	c wing 2 camera install b wing 2 camera install total 4 cameras install all camera working okk																							