Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE2089 **Priority** : High **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9820606496 **No. : Technician** Atique Salmani **Technician Mobile :** 8080922984 Name : Complain 23-10-2020 11:36:12 **Ticket Type : Date & Time :** Vendor Details : Skylone Customer's Mobile : 9820606496 Irani Wadi Company Name : Name/Client Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** VDP c wing-801-install out door bell c wing-1002- swap monitor b wing-2204-intercom issue **Complain**: 801 camera installed and working ok 802 remmooved and installed in 1001 and 903 /904 not Technician vewing lobby issue resolved. and also b wing 2204 issue resolved. **Comment**: Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 801 camera installed and working ok 802 remmooved and installed in 1001 and 903 /904 not vewing lobby issue resolved. and also b wing 2204 issue resolved. **Status History : Date Time Technician Name** Status Remark Sign 23-10-2020 Atique Salmani Completed 801 camera installed and 02:09:28 working ok 802 remmooved and installed in 1001 and 903 /904 not vewing lobby issue resolved. and also b wing 2204 issue resolved. 23-10-2020 Atique Salmani New 11:36:29 23-10-2020 Atique Salmani New 11:36:12 **Previous Date Time Technician Name** Remark Complain 19-10-2020 01:25:53 Atique Salmani B Wing 504 recrimping done from duct side and readd from **History** : lobby panel and also told to flate owener How to oprate and visit 2204 B Wing client say for next visit. so.. 13-10-2020 10:08:52 Neeraj Chauhan c wing 2 camera install b wing 2 camera install total 4 cameras install all camera working okk