## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Det	taile • VE2471					
	I					
Priority:	High					
Created By:	Admin - Apurva Vajaria					
Complaint Mob. No. :	9820606496					
Technician Name :	Siddhesh Chavan		Technicia	ician Mobile : 808092298		
Ticket Type :	Complain	Date & Time :	22-12-2020 12:10:21		-	
Vendor Details :			•			
Company Name/Client Name :	Skylone	Customer's Mobile :	9820606496		Name :	Irani Wadi
Address:						
Mumbai , , , , Mał	narashtra					
AMC Details:						
Expiry Date :	01-01-1970 05:30:0	00	Type:			
Product Name :	VDP					
Complain :	c wing 103 vdp installation b wing 304 vdp re-installation charges-550 c wing 1201 lobby to home no camera view					
Technician Comment :	c wing 103 vdp installation done and c wing 1201 lobby video working ok c wing 1701 lobby video issue solved and 3 rj45 use and b wing 304 out door camera reinstall panding					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	c wing 103 vdp installation done and c wing 1201 lobby video working ok c wing 1701 lobby video issue solved and 3 rj45 use and b wing 304 out door camera reinstall panding					
Status History :	Date Time	Technician Name	Status	Remark		Sign
	23-12-2020 01:08:45	Siddhesh Chavan	Completed	c wing 103 vdp installation done and c wing 1201 lobby video working ok c wing 1701 lobby video issue solved and 3 rj45 use and b wing 304 out door camera reinstall panding		Barleth
	22-12-2020 12:10:37	Siddhesh Chavan	New			-
	22-12-2020 12:10:21	Siddhesh Chavan	New			-
Previous Complain History:	Date Time	Technician Name	Remark			
	24-07-2023 12:03:03	Atique Salmani	Lobby camera vewinng issue resolved working ok also one to one working ok.			
	05-07-2023 10:16:40	Ravi Rajbhar	c wing 1701 door bell issue relsoved only DND Mode enble or diseble seting change			