

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3073																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820606496																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	12-05-2021 03:31:09																						
Vendor Details :																									
Company Name/Client Name :	Skylone	Customer's Mobile :	9820606496	Name :	Irani Wadi																				
Address :																									
Mumbai , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	VDP																								
Complain :	701 vdp reinstallation																								
Technician Comment :	cat6 cable missing door bell to screen need to lay Cat 6 cable and need reinstalled boath Unit screen hand over to sai lesh sir C 701 .																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	cat6 cable missing door bell to screen need to lay Cat 6 cable and need reinstalled boath Unit screen hand over to sai lesh sir C 701 .																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>12-05-2021 03:46:04</td><td>Atique Salmani</td><td>Client Side</td><td>cat6 cable missing door bell to screen need to lay Cat 6 cable and need reinstalled boath Unit screen hand over to sai lesh sir C 701 .</td><td></td></tr><tr><td>12-05-2021 03:31:22</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>12-05-2021 03:31:09</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	12-05-2021 03:46:04	Atique Salmani	Client Side	cat6 cable missing door bell to screen need to lay Cat 6 cable and need reinstalled boath Unit screen hand over to sai lesh sir C 701 .		12-05-2021 03:31:22	Atique Salmani	New		-	12-05-2021 03:31:09	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
12-05-2021 03:46:04	Atique Salmani	Client Side	cat6 cable missing door bell to screen need to lay Cat 6 cable and need reinstalled boath Unit screen hand over to sai lesh sir C 701 .																						
12-05-2021 03:31:22	Atique Salmani	New		-																					
12-05-2021 03:31:09	Atique Salmani	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>24-07-2023 12:03:03</td><td>Atique Salmani</td><td>Lobby camera vewinng issue resolved working ok also one to one working ok.</td></tr><tr><td>05-07-2023 10:16:40</td><td>Ravi Rajbhar</td><td>c wing 1701 door bell issue relsoved only DND Mode enble or diseble seting change</td></tr></tbody></table>					Date Time	Technician Name	Remark	24-07-2023 12:03:03	Atique Salmani	Lobby camera vewinng issue resolved working ok also one to one working ok.	05-07-2023 10:16:40	Ravi Rajbhar	c wing 1701 door bell issue relsoved only DND Mode enble or diseble seting change											
Date Time	Technician Name	Remark																							
24-07-2023 12:03:03	Atique Salmani	Lobby camera vewinng issue resolved working ok also one to one working ok.																							
05-07-2023 10:16:40	Ravi Rajbhar	c wing 1701 door bell issue relsoved only DND Mode enble or diseble seting change																							