

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3509																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9820606496																																		
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																															
Ticket Type :	Complain	Date & Time :	28-07-2021 01:07:53																																
Vendor Details :																																			
Company Name/Client Name :	Skylone	Customer's Mobile :	9820606496	Name :	Irani Wadi																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	VDP																																		
Complain :	in flat no. c1001 vdp issue																																		
Technician Comment :	in side screen change and all working ok and flat numbering done																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	in side screen change and all working ok and flat numbering done																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>06-08-2021 04:49:41</td><td>Siddhesh Chavan</td><td>Completed</td><td>in side screen change and all working ok and flat numbering done</td><td></td></tr><tr><td>06-08-2021 04:47:50</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>28-07-2021 01:25:05</td><td>Siddhesh Chavan</td><td>Work Pending</td><td>vdp take to office for checking out door camera view to continue Bell</td><td></td></tr><tr><td>28-07-2021 01:08:07</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>28-07-2021 01:07:53</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	06-08-2021 04:49:41	Siddhesh Chavan	Completed	in side screen change and all working ok and flat numbering done		06-08-2021 04:47:50	Siddhesh Chavan	New		-	28-07-2021 01:25:05	Siddhesh Chavan	Work Pending	vdp take to office for checking out door camera view to continue Bell		28-07-2021 01:08:07	Siddhesh Chavan	New		-	28-07-2021 01:07:53	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																															
06-08-2021 04:49:41	Siddhesh Chavan	Completed	in side screen change and all working ok and flat numbering done																																
06-08-2021 04:47:50	Siddhesh Chavan	New		-																															
28-07-2021 01:25:05	Siddhesh Chavan	Work Pending	vdp take to office for checking out door camera view to continue Bell																																
28-07-2021 01:08:07	Siddhesh Chavan	New		-																															
28-07-2021 01:07:53	Siddhesh Chavan	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>06-08-2021 06:11:21</td><td>Siddhesh Chavan</td><td>lobby video issue resolved and distributor side new crimping</td></tr><tr><td>06-08-2021 05:25:50</td><td>Siddhesh Chavan</td><td>c wing 802 out door camera reinstall and working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	06-08-2021 06:11:21	Siddhesh Chavan	lobby video issue resolved and distributor side new crimping	06-08-2021 05:25:50	Siddhesh Chavan	c wing 802 out door camera reinstall and working ok																					
Date Time	Technician Name	Remark																																	
06-08-2021 06:11:21	Siddhesh Chavan	lobby video issue resolved and distributor side new crimping																																	
06-08-2021 05:25:50	Siddhesh Chavan	c wing 802 out door camera reinstall and working ok																																	