




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

| Service Status Details : VE355 | | | | | | | | | | | | | | | | | | | | | | | | | |
|---------------------------------------|---|--|--|---|------------|-----------|-----------------|--------|---------------------|------|---------------------|---------------------|-----------|--|---|---------------------|-----------|-----|--|---|---------------------|-----------|-----|--|---|
| Priority : | Low | | | | | | | | | | | | | | | | | | | | | | | | |
| Created By : | Admin - Apurva Vajaria | | | | | | | | | | | | | | | | | | | | | | | | |
| Complaint Mob. No. : | 9820606496 | | | | | | | | | | | | | | | | | | | | | | | | |
| Technician Name : | Anil Yadav | | Technician Mobile : | 8080922983 | | | | | | | | | | | | | | | | | | | | | |
| Ticket Type : | New Installation | Date & Time : | 16-09-2019 02:49:38 | | | | | | | | | | | | | | | | | | | | | | |
| Vendor Details : | | | | | | | | | | | | | | | | | | | | | | | | | |
| Company Name/Client Name : | Skylone | Customer's Mobile : | 9820606496 | Name : | Irani Wadi | | | | | | | | | | | | | | | | | | | | |
| Address : | | | | | | | | | | | | | | | | | | | | | | | | | |
| Mumbai , , , , Maharashtra | | | | | | | | | | | | | | | | | | | | | | | | | |
| AMC Details : | | | | | | | | | | | | | | | | | | | | | | | | | |
| Expiry Date : | 01-01-1970 05:30:00 | | Type : | | | | | | | | | | | | | | | | | | | | | | |
| Product Name : | VDP | | | | | | | | | | | | | | | | | | | | | | | | |
| Complain : | install pcb flat no - b/503 | | | | | | | | | | | | | | | | | | | | | | | | |
| Technician Comment : | small and big pcb installed. both PCB working condition. | | | | | | | | | | | | | | | | | | | | | | | | |
| Complain Operator : | Desktop - Apurva Vajaria | | | | | | | | | | | | | | | | | | | | | | | | |
| Remark : | small and big pcb installed. both PCB working condition. | | | | | | | | | | | | | | | | | | | | | | | | |
| Status History : | <table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>17-09-2019 05:40:04</td><td>AnilYadav</td><td>Completed</td><td>small and big pcb installed. both PCB working condition.</td><td></td></tr><tr><td>17-09-2019 02:58:19</td><td>AnilYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>16-09-2019 02:49:39</td><td>AnilYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table> | | | | | Date Time | Technician Name | Status | Remark | Sign | 17-09-2019 05:40:04 | AnilYadav | Completed | small and big pcb installed. both PCB working condition. |  | 17-09-2019 02:58:19 | AnilYadav | New | | - | 16-09-2019 02:49:39 | AnilYadav | New | | - |
| Date Time | Technician Name | Status | Remark | Sign | | | | | | | | | | | | | | | | | | | | | |
| 17-09-2019 05:40:04 | AnilYadav | Completed | small and big pcb installed. both PCB working condition. |  | | | | | | | | | | | | | | | | | | | | | |
| 17-09-2019 02:58:19 | AnilYadav | New | | - | | | | | | | | | | | | | | | | | | | | | |
| 16-09-2019 02:49:39 | AnilYadav | New | | - | | | | | | | | | | | | | | | | | | | | | |
| Previous Complain History : | <table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-11-2019 05:20:03</td><td></td><td></td></tr><tr><td>02-11-2019 10:37:40</td><td>AnilYadav</td><td>flat no. 1203 in indoor screen connect working fine. flat no. 2004 adapter was faulty. new adapter installed screen working condition now.</td></tr></tbody></table> | | | | | Date Time | Technician Name | Remark | 08-11-2019 05:20:03 | | | 02-11-2019 10:37:40 | AnilYadav | flat no. 1203 in indoor screen connect working fine. flat no. 2004 adapter was faulty. new adapter installed screen working condition now. | | | | | | | | | | | |
| Date Time | Technician Name | Remark | | | | | | | | | | | | | | | | | | | | | | | |
| 08-11-2019 05:20:03 | | | | | | | | | | | | | | | | | | | | | | | | | |
| 02-11-2019 10:37:40 | AnilYadav | flat no. 1203 in indoor screen connect working fine. flat no. 2004 adapter was faulty. new adapter installed screen working condition now. | | | | | | | | | | | | | | | | | | | | | | | |