




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3848</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9820606496																								
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																					
<b>Ticket Type :</b>	Call Basis	<b>Date &amp; Time :</b>	18-09-2021 10:16:00																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Skylone	Customer's Mobile :	9820606496	Name :	Irani Wadi																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	VDP																								
<b>Complain :</b>	c602 - outdoor reinstallation 550/- charges to be taken																								
<b>Technician Comment :</b>	c wing 2104 4"3" fether touch vdp sceen install replacement against faulty ( not charge ble basic)ok working done																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	c wing 2104 4"3" fether touch vdp sceen install replacement against faulty ( not charge ble basic)ok working done																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>18-09-2021 01:46:52</td><td>Ravi Rajbhar</td><td>Completed</td><td>c wing 2104 4"3" fether touch vdp sceen install replacement against faulty ( not charge ble basic)ok working done</td><td></td></tr><tr><td>18-09-2021 10:16:14</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>18-09-2021 10:16:00</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	18-09-2021 01:46:52	Ravi Rajbhar	Completed	c wing 2104 4"3" fether touch vdp sceen install replacement against faulty ( not charge ble basic)ok working done		18-09-2021 10:16:14	Ravi Rajbhar	New		-	18-09-2021 10:16:00	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
18-09-2021 01:46:52	Ravi Rajbhar	Completed	c wing 2104 4"3" fether touch vdp sceen install replacement against faulty ( not charge ble basic)ok working done																						
18-09-2021 10:16:14	Ravi Rajbhar	New		-																					
18-09-2021 10:16:00	Ravi Rajbhar	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>24-07-2023 12:03:03</td><td>Atique Salmani</td><td>Lobby camera vewinnng issue resolved working ok also one to one working ok.</td></tr><tr><td>05-07-2023 10:16:40</td><td>Ravi Rajbhar</td><td>c wing 1701 door bell issue relsoved only DND Mode enble or diseble seting change</td></tr></tbody></table>					Date Time	Technician Name	Remark	24-07-2023 12:03:03	Atique Salmani	Lobby camera vewinnng issue resolved working ok also one to one working ok.	05-07-2023 10:16:40	Ravi Rajbhar	c wing 1701 door bell issue relsoved only DND Mode enble or diseble seting change											
Date Time	Technician Name	Remark																							
24-07-2023 12:03:03	Atique Salmani	Lobby camera vewinnng issue resolved working ok also one to one working ok.																							
05-07-2023 10:16:40	Ravi Rajbhar	c wing 1701 door bell issue relsoved only DND Mode enble or diseble seting change																							