

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE393																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9820606496																																		
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																															
Ticket Type :	Complain	Date & Time :	21-09-2019 10:06:40																																
Vendor Details :																																			
Company Name/Client Name :	Skylone	Customer's Mobile :	9820606496	Name :	Irani Wadi																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	VDP																																		
Complain :	1904 1604 2203 1601 vdp issue																																		
Technician Comment :	2203 vdp recantion and 1904 1601 1604 wdp check and working ok																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	2203 vdp recantion and 1904 1601 1604 wdp check and working ok																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-09-2019 12:02:32</td><td>Siddhesh Chavan</td><td>Completed</td><td>2203 vdp recantion and 1904 1601 1604 wdp check and working ok</td><td></td></tr><tr><td>25-09-2019 10:34:48</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>21-09-2019 11:34:14</td><td>Siddhesh Chavan</td><td>Work Pending</td><td>2203 screen under repair 1904 lock 1601 1604 continue ringing but when visit working ok.</td><td></td></tr><tr><td>21-09-2019 10:06:43</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>21-09-2019 10:06:40</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-09-2019 12:02:32	Siddhesh Chavan	Completed	2203 vdp recantion and 1904 1601 1604 wdp check and working ok		25-09-2019 10:34:48	Siddhesh Chavan	New		-	21-09-2019 11:34:14	Siddhesh Chavan	Work Pending	2203 screen under repair 1904 lock 1601 1604 continue ringing but when visit working ok.		21-09-2019 10:06:43	Siddhesh Chavan	New		-	21-09-2019 10:06:40	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																															
25-09-2019 12:02:32	Siddhesh Chavan	Completed	2203 vdp recantion and 1904 1601 1604 wdp check and working ok																																
25-09-2019 10:34:48	Siddhesh Chavan	New		-																															
21-09-2019 11:34:14	Siddhesh Chavan	Work Pending	2203 screen under repair 1904 lock 1601 1604 continue ringing but when visit working ok.																																
21-09-2019 10:06:43	Siddhesh Chavan	New		-																															
21-09-2019 10:06:40	Siddhesh Chavan	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-11-2019 05:20:03</td><td></td><td></td></tr><tr><td>02-11-2019 10:37:40</td><td>AnilYadav</td><td>flat no. 1203 in indoor screen connect working fine. flat no. 2004 adapter was faulty. new adapter installed screen working condition now.</td></tr></tbody></table>					Date Time	Technician Name	Remark	08-11-2019 05:20:03			02-11-2019 10:37:40	AnilYadav	flat no. 1203 in indoor screen connect working fine. flat no. 2004 adapter was faulty. new adapter installed screen working condition now.																					
Date Time	Technician Name	Remark																																	
08-11-2019 05:20:03																																			
02-11-2019 10:37:40	AnilYadav	flat no. 1203 in indoor screen connect working fine. flat no. 2004 adapter was faulty. new adapter installed screen working condition now.																																	