## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE6606 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9820606496 **No. : Technician** Siddhesh Chavan **Technician Mobile :** 8080922985 Name : Complain 17-10-2022 12:53:55 **Ticket Type :** Date & Time : Vendor Details : Customer's Mobile : 9820606496 Irani Wadi Company Skylone Name : Name/Client Name Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** Access **Complain**: Door lock system not working in both wings c wing lobby panel install and display working okay and calling working okay and door Technician **Comment** : alignment issue for client side Complain Desktop - Apurva Vajaria **Operator** : **Remark** : c wing lobby panel install and display working okay and calling working okay and door alignment issue for client side **Status History : Date Time Technician Name** Status Remark Sign 20-10-2022 Siddhesh Chavan New 02:35:33 18-10-2022 Siddhesh Chavan Client Side c wing lobby panel install 04:01:10 and display working okay (M) and calling working okay and door alignment issue for client side 18-10-2022 Siddhesh Chavan New 03:34:24 Rady 17-10-2022 Siddhesh Chavan Work c wing lobby panel display 04:29:22 Pending issue and lobby panel take to office for checking and b wing 1504 vdp Take to office for checking because vdp continue bell and boh wing door alignment need to set door 17-10-2022 Siddhesh Chavan New 12:54:12 17-10-2022 Siddhesh Chavan New 12:53:55

Previous Complain History :	Date Time	Technician Name	Remark
	24-07-2023 12:03:03	Atique Salmani	Lobby camera vewinng issue resolved working ok also one to one working ok.
	05-07-2023 10:16:40	Ravi Rajbhar	c wing 1701 door bell issue relsoved only DND Mode enble or diseble seting change