

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | **W :** www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE4605					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	7400084949				
Technician Name :	Anil Yadav		Technician Mobile :	8090436743	
Ticket Type :	New Installation	Date & Time :	18-01-2022 10:51:18		
Vendor Details :					
Company Name/Client Name :	Bhavesht - Nair	Customer's Mobile :	7400084949	Name :	J B Boda And Company Pvt Ltd
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	Fire				
Complain :	In Basement New Installation of fire alarm system				
Technician Comment :	Cable loop clear but one detector new requirement.				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	Cable loop clear but one detector new requirement.				

Status History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr><tr><td>11-04-2022 04:29:33</td><td>Anil Yadav</td><td>Work Pending</td><td>Cable loop clear but one detector new requirement.</td><td></td></tr><tr><td>28-03-2022 02:52:23</td><td>Anil Yadav</td><td>Client Side</td><td>Detected no. 7 to Detector no. 8 cable continuety not finding so issue not resolve. One em lock complain closed.</td><td></td></tr><tr><td>28-03-2022 10:56:16</td><td>Anil Yadav</td><td>New</td><td></td><td>-</td></tr><tr><td>07-03-2022 10:24:51</td><td>Anil Yadav</td><td>New</td><td></td><td>-</td></tr><tr><td>04-03-2022 10:00:08</td><td>Anil Yadav</td><td>New</td><td></td><td>-</td></tr><tr><td>24-02-2022 03:43:01</td><td>Anil Yadav</td><td>Client Side</td><td>8 S.D. installed with connection and MCP hooter and one detector cable painding .also told slot for MCP and hooter according to vision sir .</td><td></td></tr><tr><td>24-02-2022 10:52:37</td><td>Anil Yadav</td><td>New</td><td></td><td>-</td></tr><tr><td>18-01-2022 11:14:19</td><td>Anil Yadav</td><td>New</td><td></td><td>-</td></tr><tr><td>18-01-2022 10:51:18</td><td>Anil Yadav</td><td>New</td><td></td><td>-</td></tr></table>	Date Time	Technician Name	Status	Remark	Sign	11-04-2022 04:29:33	Anil Yadav	Work Pending	Cable loop clear but one detector new requirement.		28-03-2022 02:52:23	Anil Yadav	Client Side	Detected no. 7 to Detector no. 8 cable continuety not finding so issue not resolve. One em lock complain closed.		28-03-2022 10:56:16	Anil Yadav	New		-	07-03-2022 10:24:51	Anil Yadav	New		-	04-03-2022 10:00:08	Anil Yadav	New		-	24-02-2022 03:43:01	Anil Yadav	Client Side	8 S.D. installed with connection and MCP hooter and one detector cable painding .also told slot for MCP and hooter according to vision sir .		24-02-2022 10:52:37	Anil Yadav	New		-	18-01-2022 11:14:19	Anil Yadav	New		-	18-01-2022 10:51:18	Anil Yadav	New		-
	Date Time	Technician Name	Status	Remark	Sign																																														
	11-04-2022 04:29:33	Anil Yadav	Work Pending	Cable loop clear but one detector new requirement.																																															
	28-03-2022 02:52:23	Anil Yadav	Client Side	Detected no. 7 to Detector no. 8 cable continuety not finding so issue not resolve. One em lock complain closed.																																															
	28-03-2022 10:56:16	Anil Yadav	New		-																																														
	07-03-2022 10:24:51	Anil Yadav	New		-																																														
	04-03-2022 10:00:08	Anil Yadav	New		-																																														
	24-02-2022 03:43:01	Anil Yadav	Client Side	8 S.D. installed with connection and MCP hooter and one detector cable painding .also told slot for MCP and hooter according to vision sir .																																															
	24-02-2022 10:52:37	Anil Yadav	New		-																																														
	18-01-2022 11:14:19	Anil Yadav	New		-																																														
18-01-2022 10:51:18	Anil Yadav	New		-																																															
Previous Complain History :	<table><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr><tr><td>25-07-2023 12:50:20</td><td>ChandanYadav</td><td>1st floor Essl system hang ieesu and check the office.</td></tr><tr><td>14-07-2023 10:54:46</td><td>Siddhesh Chavan</td><td>6 th floor one biometric machine take to office for checking because machine hang and temporary install another machine</td></tr></table>					Date Time	Technician Name	Remark	25-07-2023 12:50:20	ChandanYadav	1st floor Essl system hang ieesu and check the office.	14-07-2023 10:54:46	Siddhesh Chavan	6 th floor one biometric machine take to office for checking because machine hang and temporary install another machine																																					
Date Time	Technician Name	Remark																																																	
25-07-2023 12:50:20	ChandanYadav	1st floor Essl system hang ieesu and check the office.																																																	
14-07-2023 10:54:46	Siddhesh Chavan	6 th floor one biometric machine take to office for checking because machine hang and temporary install another machine																																																	