Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E : vallabhsecure@yah	100.00.111							
Service Status De	tails : VE7667							
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	9920420594							
Technician Name :	Sonu Kumar			Technician M	8454016444	8454016444		
Ticket Type :	Complain	Date & Time :		17-02-2023 02:33:11				
Vendor Details :	-							
Company Name/Client Name :	Matunga Kamal Kunj Society	Customer's Mobil :	le	9920420594		Name :	Jayprakash Kiran Sir Joy	
Address:								
Mumbai , , , , Mal	narashtra							
AMC Details :	_							
Expiry Date :	01-01-1970 05:30:00			Type:				
Product Name:	Time And Attendance							
Complain:	repaired Biometric Device need to do install							
Technician Comment :	Time and attendence machine not installed handover to laxman sir							
Complain Operator :	Desktop - Apurva Vajaria							
Remark:	Time and attendence machine not installed handover to laxman sir Sonu visited on 18.02.2022 with adapter device installed							
Status History :	Date Time	Technician Nan	ne	Status	Remark			Sign
	21-02-2023 03:17:4	9 Sonu Kumar	Sonu Kumar					-
	18-02-2023 10:39:0	2 Sonu Kumar	Sonu Kumar					-
	17-02-2023 06:05:1	Sonu Kumar		Work Pending	Time and attendence machine not installed handover to laxman sir		r	JUR .
	17-02-2023 02:46:0	0 Sonu Kumar		New				-
Previous Complain History :	Date Time	Technician Name		Remark				
	11-02-2023 10:20:53	Ravi Rajbhar	d	Kamal kunj second lift intercom issue resolved and ok working done cable check with lift parson cable one pair breck then second pair used then ok working done all system ok working				
	04-02-2023 11:10:05	Ravi Rajbhar	A o h	Vdp work completed smae poe injector faulty and all flat vdp check and ok working done All acesss door check all ok working And cctv camera check bandwidth issues resolved and ok working one camera connector faulty main gate and camera remove and hondover to society office and reception camera. Faulty and handover to society office				