




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7712																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9920420594																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	23-02-2023 11:17:26																	
Vendor Details :																				
Company Name/Client Name :	Matunga Kamal Kunj Society	Customer's Mobile :	9920420594	Name :	Jayprakash Kiran Sir Joy															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	VDP																			
Complain :	13th and 14th floor vdp bell continuous ringing issue																			
Technician Comment :	14 th floor and 13 floor vdp sceen continue rining issue resolved but both sceen under observation 2- 3 day And 1302 sceen remove and hondover to society office becz client not at home afternoon																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	14 th floor and 13 floor vdp sceen continue rining issue resolved but both sceen under observation 2- 3 day And 1302 sceen remove and hondover to society office becz client not at home afternoon																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>23-02-2023 02:10:15</td><td>Ravi Rajbhar</td><td>Completed</td><td>14 th floor and 13 floor vdp sceen continue rining issue resolved but both sceen under observation 2- 3 day And 1302 sceen remove and hondover to society office becz client not at home afternoon</td><td></td></tr><tr><td>23-02-2023 11:17:35</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	23-02-2023 02:10:15	Ravi Rajbhar	Completed	14 th floor and 13 floor vdp sceen continue rining issue resolved but both sceen under observation 2- 3 day And 1302 sceen remove and hondover to society office becz client not at home afternoon		23-02-2023 11:17:35	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
23-02-2023 02:10:15	Ravi Rajbhar	Completed	14 th floor and 13 floor vdp sceen continue rining issue resolved but both sceen under observation 2- 3 day And 1302 sceen remove and hondover to society office becz client not at home afternoon																	
23-02-2023 11:17:35	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>17-02-2023 02:33:11</td><td>Sonu Kumar</td><td>Time and attendance machine not installed handover to laxman sir Sonu visited on 18.02.2022 with adapter device installed</td></tr><tr><td>11-02-2023 10:20:53</td><td>Ravi Rajbhar</td><td>Kamal kunj second lift intercom issue resolved and ok working done cable check with lift parson cable one pair breck then second pair used then ok working done all system ok working</td></tr></tbody></table>					Date Time	Technician Name	Remark	17-02-2023 02:33:11	Sonu Kumar	Time and attendance machine not installed handover to laxman sir Sonu visited on 18.02.2022 with adapter device installed	11-02-2023 10:20:53	Ravi Rajbhar	Kamal kunj second lift intercom issue resolved and ok working done cable check with lift parson cable one pair breck then second pair used then ok working done all system ok working						
Date Time	Technician Name	Remark																		
17-02-2023 02:33:11	Sonu Kumar	Time and attendance machine not installed handover to laxman sir Sonu visited on 18.02.2022 with adapter device installed																		
11-02-2023 10:20:53	Ravi Rajbhar	Kamal kunj second lift intercom issue resolved and ok working done cable check with lift parson cable one pair breck then second pair used then ok working done all system ok working																		