




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7976																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9920420594																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	28-03-2023 10:32:40																	
Vendor Details :																				
Company Name/Client Name :	Matunga Kamal Kunj Society	Customer's Mobile :	9920420594	Name :	Jayprakash Kiran Sir Joy															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Intercom																			
Complain :	Security cabin intercom issue																			
Technician Comment :	security cabin main gate intercom issue resolved 97 cable joint reception and cable one pair change and rejoined in reception then ok working done																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	security cabin main gate intercom issue resolved 97 cable joint reception and cable one pair change and rejoined in reception then ok working done																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>28-03-2023 03:16:47</td><td>Ravi Rajbhar</td><td>Completed</td><td>security cabin main gate intercom issue resolved 97 cable joint reception and cable one pair change and rejoined in reception then ok working done</td><td></td></tr><tr><td>28-03-2023 10:32:47</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	28-03-2023 03:16:47	Ravi Rajbhar	Completed	security cabin main gate intercom issue resolved 97 cable joint reception and cable one pair change and rejoined in reception then ok working done		28-03-2023 10:32:47	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
28-03-2023 03:16:47	Ravi Rajbhar	Completed	security cabin main gate intercom issue resolved 97 cable joint reception and cable one pair change and rejoined in reception then ok working done																	
28-03-2023 10:32:47	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-04-2023 10:17:06</td><td>Ravi Rajbhar</td><td>main gate security ex.no.97 line check rejoined cable and gateway sitde check connection all ex. ok working done check some flat calling to flat</td></tr><tr><td>11-03-2023 02:28:23</td><td>Ravi Rajbhar</td><td>901 intercom issue resolved but temporary going on other number 1601 and two camera camera no video check one camera ok working or one camera connector issue then remove the same camera and collect camera confrim to falguni mdm</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-04-2023 10:17:06	Ravi Rajbhar	main gate security ex.no.97 line check rejoined cable and gateway sitde check connection all ex. ok working done check some flat calling to flat	11-03-2023 02:28:23	Ravi Rajbhar	901 intercom issue resolved but temporary going on other number 1601 and two camera camera no video check one camera ok working or one camera connector issue then remove the same camera and collect camera confrim to falguni mdm						
Date Time	Technician Name	Remark																		
19-04-2023 10:17:06	Ravi Rajbhar	main gate security ex.no.97 line check rejoined cable and gateway sitde check connection all ex. ok working done check some flat calling to flat																		
11-03-2023 02:28:23	Ravi Rajbhar	901 intercom issue resolved but temporary going on other number 1601 and two camera camera no video check one camera ok working or one camera connector issue then remove the same camera and collect camera confrim to falguni mdm																		