




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | **W :** www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8185																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9920420594																			
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																
Ticket Type :	Complain	Date & Time :	24-04-2023 10:40:45																	
Vendor Details :																				
Company Name/Client Name :	Matunga Kamal Kunj Society	Customer's Mobile :	9920420594	Name :	Jayprakash Kiran Sir Joy															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	cCTV-Intercom																			
Complain :	Roadside 1 repaired camera need to install and flat no. 901 intercom issue																			
Technician Comment :	road side one bullet ip camera install and working ok and 901 intercom issue resolved and trage side one camera install new 4*4 box and sip system repogram 1302 vdp reinstall and working ok																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	road side one bullet ip camera install and working ok and 901 intercom issue resolved and trage side one camera install new 4*4 box and sip system repogram 1302 vdp reinstall and working ok																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-04-2023 04:59:21</td><td>Siddhesh Chavan</td><td>Completed</td><td>road side one bullet ip camera install and working ok and 901 intercom issue resolved and trage side one camera install new 4*4 box and sip system repogram 1302 vdp reinstall and working ok</td><td></td></tr><tr><td>24-04-2023 10:40:55</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-04-2023 04:59:21	Siddhesh Chavan	Completed	road side one bullet ip camera install and working ok and 901 intercom issue resolved and trage side one camera install new 4*4 box and sip system repogram 1302 vdp reinstall and working ok		24-04-2023 10:40:55	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																
24-04-2023 04:59:21	Siddhesh Chavan	Completed	road side one bullet ip camera install and working ok and 901 intercom issue resolved and trage side one camera install new 4*4 box and sip system repogram 1302 vdp reinstall and working ok																	
24-04-2023 10:40:55	Siddhesh Chavan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-04-2023 10:17:06</td><td>Ravi Rajbhar</td><td>main gate security ex.no.97 line check rejoined cable and gateway sitde check connection all ex. ok working done check some flat calling to flat</td></tr><tr><td>28-03-2023 10:32:40</td><td>Ravi Rajbhar</td><td>security cabin main gate intercom issue resolved 97 cable joint recepation and cable one pair change and rejoined in recepation then ok working done</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-04-2023 10:17:06	Ravi Rajbhar	main gate security ex.no.97 line check rejoined cable and gateway sitde check connection all ex. ok working done check some flat calling to flat	28-03-2023 10:32:40	Ravi Rajbhar	security cabin main gate intercom issue resolved 97 cable joint recepation and cable one pair change and rejoined in recepation then ok working done						
Date Time	Technician Name	Remark																		
19-04-2023 10:17:06	Ravi Rajbhar	main gate security ex.no.97 line check rejoined cable and gateway sitde check connection all ex. ok working done check some flat calling to flat																		
28-03-2023 10:32:40	Ravi Rajbhar	security cabin main gate intercom issue resolved 97 cable joint recepation and cable one pair change and rejoined in recepation then ok working done																		