## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

I								
Service Status Det	cails: VE9654							
Priority:	Low							
Created By:	Admin - Apurva Vajaria							
Complaint Mob. No. :	9920420594							
Technician Name :	Ravi Rajbhar		Technici	an Mobile 8080922965				
Ticket Type :	AMC visiting	Date & Time :	27-09-20	23 01:28:33	33			
Vendor Details :								
Company Name/Client Name :	Matunga Kamal Kunj Society	Customer's Mobile :	9920420	594	Name:	Jaypı Sir Jo	rakash Kiran y	
Address:								
Mumbai , , , , Mah	narashtra							
AMC Details :								
Expiry Date :	01-01-1970 05:30	Type:	Type:					
<b>Product Name:</b>	Ppm							
Complain :	CCTV/VDP/Access Control System/Time and Attendance PPM Need to do							
Technician Comment :	ppm done of cctv syatam , access , intercom and video door phone all ok working done one camera remove and take to office bcz camera connector issue (besment camera ) and sarvice lift cctv cmaera sarvey done							
Complain Operator :	Desktop - Apurva Vajaria							
Remark :	ppm done of cctv syatam , access , intercom and video door phone all ok working done one camera remove and take to office bcz camera connector issue (besment camera) and sarvice lift cctv cmaera sarvey done							
<b>Status History :</b>	Date Time	Technician Name	Status	Remark		Sign		
	27-09-2023 02:06:06	Ravi Rajbhar	Completed	ppm done of cctv syatam , access , intercom and video door phone all ok working done one camera remove and take to office bcz camera connector issue ( besment camera ) and sarvice lift cctv cmaera sarvey done		anza		
	27-09-2023 01:28:40	Ravi Rajbhar	New				-	
Previous Complain History :	Date Time Technician Name		ne	Remark				
	28-10-2023 12:49:0	4 Sonu Kumar	Kumar Recording seen by laxman ji					
	16-10-2023 12:40:5	2 Ravi Rajbhar			tercom ok working done and second lift need to able then check intercom in lift second lift cable 90 approx			