Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status De	tails: VE2787						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9324606050						
Technician Name :	Neeraj Chauhan		Techni	ician Mobile : 8898885764			
Ticket Type :	Complain Date & Time :		08-03-2	08-03-2021 10:06:59			
Vendor Details :							
Company Name/Client Name :	New Orchid Plaza	Customer's Mobile	e: 932460	06050	Name :	Jinal	
Address:							
Mumbai,,,, Maharashtra							
AMC Details :							
Expiry Date :	01-01-1970 05:30:00 Type:						
Product Name:	Ppm						
Complain:	cctv						
Technician Comment :	pm work completed of all cameras and screaming functioning OK recording of both DVr also showing no of days as required by client one outdoor camera bullet removed coz of renovation work bullet camera handover to security guard						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	pm work completed of all cameras and screaming functioning OK recording of both DVr also showing no of days as required by client one outdoor camera bullet removed coz of renovation work bullet camera handover to security guard						
Status History :	Date Time	Technician Name	Status	Remark		Sign	
	08-03-2021 12:32:48	Neeraj Chauhan	Completed	pm work completed of all cameras and screaming functioning OK recording of both DVr also showing no of days as required by client one outdoor camera bullet removed coz of renovation work bullet camera handover to security guard		Par	
	08-03-2021 10:07:17	Neeraj Chauhan	New			-	
	08-03-2021 10:07:00	Neeraj Chauhan	New			-	

Previous
Complain
History :

Date Time	Technician Name	Remark
24-03-2022 10:18:15	Atique Salmani	lift cabling done 56 meter working ok.
19-03-2022 10:20:36	Siddhesh Chavan	one camera no video issue resolved 7 th floor cable joined and 7 th floor lift side camera issue because camera cable cut by mouse and need to change camera one camera lining issue resolved