

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3205																																								
Priority :	Low																																							
Created By :	Admin - Apurva Vajaria																																							
Complaint Mob. No. :	9324606050																																							
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																																				
Ticket Type :	Complain	Date & Time :	07-06-2021 11:52:17																																					
Vendor Details :																																								
Company Name/Client Name :	New Orchid Plaza	Customer's Mobile :	9324606050	Name :	Jinal																																			
Address :																																								
Mumbai , , , , Maharashtra																																								
AMC Details :																																								
Expiry Date :	01-01-1970 05:30:00		Type :																																					
Product Name :	Ppm																																							
Complain :	CCTV																																							
Technician Comment :	new adpetar install and one bullet camera reinstall and all camera working ok																																							
Complain Operator :	Desktop - Apurva Vajaria																																							
Remark :	new adpetar install and one bullet camera reinstall and all camera working ok																																							
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-06-2021 05:18:35</td><td>Siddhesh Chavan</td><td>Completed</td><td>new adpetar install and one bullet camera reinstall and all camera working ok</td><td></td></tr><tr><td>09-06-2021 10:08:23</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>07-06-2021 08:24:46</td><td>Siddhesh Chavan</td><td>Work Pending</td><td>ppm done and all camera clinling done and 2 camera no video issue resolved and 8 & 9 MTR use and lift camera adepter issue and out side camera reinstall pending</td><td></td></tr><tr><td>07-06-2021 06:37:55</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>07-06-2021 11:52:28</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>07-06-2021 11:52:17</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-06-2021 05:18:35	Siddhesh Chavan	Completed	new adpetar install and one bullet camera reinstall and all camera working ok		09-06-2021 10:08:23	Siddhesh Chavan	New		-	07-06-2021 08:24:46	Siddhesh Chavan	Work Pending	ppm done and all camera clinling done and 2 camera no video issue resolved and 8 & 9 MTR use and lift camera adepter issue and out side camera reinstall pending		07-06-2021 06:37:55	Siddhesh Chavan	New		-	07-06-2021 11:52:28	Siddhesh Chavan	New		-	07-06-2021 11:52:17	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																																				
10-06-2021 05:18:35	Siddhesh Chavan	Completed	new adpetar install and one bullet camera reinstall and all camera working ok																																					
09-06-2021 10:08:23	Siddhesh Chavan	New		-																																				
07-06-2021 08:24:46	Siddhesh Chavan	Work Pending	ppm done and all camera clinling done and 2 camera no video issue resolved and 8 & 9 MTR use and lift camera adepter issue and out side camera reinstall pending																																					
07-06-2021 06:37:55	Siddhesh Chavan	New		-																																				
07-06-2021 11:52:28	Siddhesh Chavan	New		-																																				
07-06-2021 11:52:17	Siddhesh Chavan	New		-																																				

Previous Complain History :	Date Time	Technician Name	Remark
	24-03-2022 10:18:15	Atique Salmani	lift cabling done 56 meter working ok.
	19-03-2022 10:20:36	Siddhesh Chavan	one camera no video issue resolved 7 th floor cable joined and 7 th floor lift side camera issue because camera cable cut by mouse and need to change camera one camera lining issue resolved