

# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE11220</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9819662812																								
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	26-03-2024 11:43:27																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Bellavista Building	Customer's Mobile :	9819662812	Name :	Jivan Patil																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	31-08-2021 12:00:00		Type :	Non-Comprehensive																					
<b>Product Name :</b>	VDP																								
<b>Complain :</b>	1)flat no. 1001 VDP need to reinstallation need to do - 750/- visiting charges 2)flat no. 1003 - intercom issue																								
<b>Technician Comment :</b>	1001 video door phone reinstallation pending client site bcz duct to flat cable missing 1003 line ok no instrument and one car lift cmaera issue resolved and ok working done																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	1001 video door phone reinstallation pending client site bcz duct to flat cable missing 1003 line ok no instrument and one car lift cmaera issue resolved and ok working done																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>08-04-2024 04:03:44</td><td>Ravi Rajbhar</td><td>Client Side</td><td>1001 video door phone reinstallation pending client site bcz duct to flat cable missing 1003 line ok no instrument and one car lift cmaera issue resolved and ok working done</td><td></td></tr><tr><td>08-04-2024 10:02:54</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>29-03-2024 06:24:14</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	08-04-2024 04:03:44	Ravi Rajbhar	Client Side	1001 video door phone reinstallation pending client site bcz duct to flat cable missing 1003 line ok no instrument and one car lift cmaera issue resolved and ok working done		08-04-2024 10:02:54	Ravi Rajbhar	New		-	29-03-2024 06:24:14	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
08-04-2024 04:03:44	Ravi Rajbhar	Client Side	1001 video door phone reinstallation pending client site bcz duct to flat cable missing 1003 line ok no instrument and one car lift cmaera issue resolved and ok working done																						
08-04-2024 10:02:54	Ravi Rajbhar	New		-																					
29-03-2024 06:24:14	Ravi Rajbhar	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>16-04-2024 09:57:54</td><td>Sonu Kumar</td><td></td></tr><tr><td>14-03-2024 10:26:36</td><td>Siddhesh Chavan</td><td>cctv Intercom working ok all camera working ok ppm done</td></tr></tbody></table>					Date Time	Technician Name	Remark	16-04-2024 09:57:54	Sonu Kumar		14-03-2024 10:26:36	Siddhesh Chavan	cctv Intercom working ok all camera working ok ppm done											
Date Time	Technician Name	Remark																							
16-04-2024 09:57:54	Sonu Kumar																								
14-03-2024 10:26:36	Siddhesh Chavan	cctv Intercom working ok all camera working ok ppm done																							