Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE3088 **Priority** : Low **Created By :** Admin - Apurva Vajaria Complaint 9819662812 Mob. No. : Technician Yogesh Desai **Technician Mobile :** 8080922963 Name : Complain Date & Time : 15-05-2021 12:50:46 **Ticket Type : Vendor Details :** Customer's Mobile Jivan Patil Bellavista 9819662812 Company Name : Name/Client Building Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 31-08-2021 12:00:00 Non-Comprehensive Expiry Date : Type : **Product Name :** CCTV **Complain**: cctv system not working CCTV system working ok all three dvr are working camera connected to them also working **Technician** recording is on playback aslo can be seen There was to power issue and hdmi cable was loose **Comment** : hdmi issue Now everything is working all cameras can be seen on tv. Complain Desktop - Apurva Vajaria **Operator** : **Remark** : CCTV system working ok all three dvr are working camera connected to them also working recording is on playback aslo can be seen There was to power issue and hdmi cable was loose hdmi issue Now everything is working all cameras can be seen on tv. **Status History : Date Time Technician Name** Status Remark Sign 15-05-2021 CCTV system working ok all three YogeshDesai Completed 04:07:20 dvr are working camera connected to them also working recording is on playback aslo can be seen There was tv power issue and hdmi cable was loose hdmi issue Now everything is working all cameras can be seen on tv 15-05-2021 YogeshDesai New 12:51:01 15-05-2021 YogeshDesai New 12:50:46

Previous Complain History :	Date Time	Technician Name	Remark
	08-08-2023 11:34:18	DilshadKhan	In screen cameras not changing issu in $2+2$ $4+1$ cabal 2 mtr and 2 rc pin work pending
	01-08-2023 10:50:00	Siddhesh Chavan	2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on off issue resoved and 7th floor reception intrcom issue resolved cantion side recontion