




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3218</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9819662812																								
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	10-06-2021 10:07:50																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Bellavista Building	<b>Customer's Mobile :</b>	9819662812	<b>Name :</b>	Jivan Patil																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	31-08-2021 12:00:00		<b>Type :</b>	Non-Comprehensive																					
<b>Product Name :</b>	Intercom																								
<b>Complain :</b>	outgoing from lobby is not working																								
<b>Technician Comment :</b>	lobby 91 intercom issue resolved and ok working done only cable issue 1601 issue resolved 1302 port issue resolved and ok working( new port uesd) 1204 line ok instrument issue 1102 issue resolved																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	lobby 91 intercom issue resolved and ok working done only cable issue 1601 issue resolved 1302 port issue resolved and ok working( new port uesd) 1204 line ok instrument issue 1102 issue resolved																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-06-2021 03:08:25</td><td>Ravi Rajbhar</td><td>Completed</td><td>lobby 91 intercom issue resolved and ok working done only cable issue 1601 issue resolved 1302 port issue resolved and ok working( new port uesd) 1204 line ok instrument issue 1102 issue resolved</td><td></td></tr><tr><td>10-06-2021 10:08:02</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>10-06-2021 10:07:50</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-06-2021 03:08:25	Ravi Rajbhar	Completed	lobby 91 intercom issue resolved and ok working done only cable issue 1601 issue resolved 1302 port issue resolved and ok working( new port uesd) 1204 line ok instrument issue 1102 issue resolved		10-06-2021 10:08:02	Ravi Rajbhar	New		-	10-06-2021 10:07:50	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
10-06-2021 03:08:25	Ravi Rajbhar	Completed	lobby 91 intercom issue resolved and ok working done only cable issue 1601 issue resolved 1302 port issue resolved and ok working( new port uesd) 1204 line ok instrument issue 1102 issue resolved																						
10-06-2021 10:08:02	Ravi Rajbhar	New		-																					
10-06-2021 10:07:50	Ravi Rajbhar	New		-																					

Previous Complain History :			
	Date Time	Technician Name	Remark
	08-08-2023 11:34:18	DilshadKhan	In screen cameras not changing issu in 2+2 4+1 cabal 2 mtr and 2 rc pin work pending
	01-08-2023 10:50:00	Siddhesh Chavan	2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on off issue resoved and 7th floor reception intrcom issue resolved cantion side recontion