Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status De	staile · VE2220						
Priority:		Low					
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No.:	9819662812						
Technician Name :	Neeraj Chauhan		Technicia :	nician Mobile 8898885764			
Ticket Type :	New Installation Date & Time :		28-06-2021 01:59:09				
Vendor Details:			•		<u>.</u>		
Company Name/Client Name :	Bellavista Building	Customer's Mobile :	98196628	312	Name :	Jivan Patil	
Address:							
Mumbai , , , , Ma	harashtra						
AMC Details :							
Expiry Date :	31-08-2021 12:00:0	Type: Non-Comprehensive		sive			
Product Name:	CCTV						
Complain:	rack installation with cable dressing						
Technician Comment :	1 new 4u rak install and old rake reinstall and 3 dvr reinstall and came working okk and 1 lift cable issue lift number 2 1 new hdmi install 5 mtr and work done						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	1 new 4u rak install and old rake reinstall and 3 dvr reinstall and came working okk and 1 lift cable issue lift number 2 1 new hdmi install 5 mtr and work done						
Status History :	Date Time	Technician Name	Status	Remark		Sign	
	01-07-2021 07:20:02	Neeraj Chauhan	Completed	reinstall an came worki cable issue	ak install and old rake d 3 dvr reinstall and ng okk and 1 lift lift number 2 1 new l 5 mtr and work	[[]	
	30-06-2021 11:17:16	Neeraj Chauhan	New			-	
	30-06-2021 12:40:01	Neeraj Chauhan	New			-	
	28-06-2021 01:59:27	Neeraj Chauhan	New			-	
	28-06-2021 01:59:25	Neeraj Chauhan	New			-	
	28-06-2021 01:59:09	Neeraj Chauhan	New			-	

Previous
Complain
History :

Date Time	Technician Name	Remark	
08-08-2023 11:34:18	DilshadKhan	In screen cameras not changing issu in $2+2\ 4+1$ cabal 2 mtr and 2 rc pin work pending	
01-08-2023 10:50:00	Siddhesh Chavan	2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on o issue resoved and 7th floor reception intrcom issue resolved cantion side recontion	