




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3680</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9819662812																								
<b>Technician Name :</b>	Yogesh Desai		<b>Technician Mobile :</b>	8080922963																					
<b>Ticket Type :</b>	Call Basis	<b>Date &amp; Time :</b>	23-08-2021 12:12:50																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Bellavista Building	Customer's Mobile :	9819662812	Name :	Jivan Patil																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	31-08-2021 12:00:00		<b>Type :</b>	Non-Comprehensive																					
<b>Product Name :</b>	Intercom																								
<b>Complain :</b>	902 phone installation - 550 cash to be collected																								
<b>Technician Comment :</b>	New beetel wall mount phone installed in flat no 902. And cash received from client.550.																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	New beetel wall mount phone installed in flat no 902. And cash received from client.550.																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>23-08-2021 12:58:26</td><td>YogeshDesai</td><td>Completed</td><td>New beetel wall mount phone installed in flat no 902. And cash received from client.550.</td><td></td></tr><tr><td>23-08-2021 12:13:12</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr><tr><td>23-08-2021 12:12:50</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	23-08-2021 12:58:26	YogeshDesai	Completed	New beetel wall mount phone installed in flat no 902. And cash received from client.550.		23-08-2021 12:13:12	YogeshDesai	New		-	23-08-2021 12:12:50	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																					
23-08-2021 12:58:26	YogeshDesai	Completed	New beetel wall mount phone installed in flat no 902. And cash received from client.550.																						
23-08-2021 12:13:12	YogeshDesai	New		-																					
23-08-2021 12:12:50	YogeshDesai	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>08-08-2023 11:34:18</td><td>DilshadKhan</td><td>In screen cameras not changing issu in 2+2 4+1 cabal 2 mtr and 2 rc pin work pending</td></tr><tr><td>01-08-2023 10:50:00</td><td>Siddhesh Chavan</td><td>2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on off issue resoved and 7th floor reception intrcom issue resolved cantion side recontion</td></tr></tbody></table>					Date Time	Technician Name	Remark	08-08-2023 11:34:18	DilshadKhan	In screen cameras not changing issu in 2+2 4+1 cabal 2 mtr and 2 rc pin work pending	01-08-2023 10:50:00	Siddhesh Chavan	2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on off issue resoved and 7th floor reception intrcom issue resolved cantion side recontion											
Date Time	Technician Name	Remark																							
08-08-2023 11:34:18	DilshadKhan	In screen cameras not changing issu in 2+2 4+1 cabal 2 mtr and 2 rc pin work pending																							
01-08-2023 10:50:00	Siddhesh Chavan	2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on off issue resoved and 7th floor reception intrcom issue resolved cantion side recontion																							