Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E: vanabiisecure@ya							
Service Status De	etails : VE9037						
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9819662812						
Technician Name :	Siddhesh Chavan		Technician Mobile 8080922985				
Ticket Type :	Complain	Date & Time :	01-08-2023 10:50:00				
Vendor Details :	-		•				
Company Name/Client Name :	Bellavista Building	Customer's Mobile :	9819662812		Name :	Jivan Patil	
Address:							
Mumbai , , , , Ma	harashtra						
AMC Details:							
Expiry Date :	31-08-2021 12:00:0	00	Type:		Non-Comprehensive		
Product Name:	CCTV		•				
Complain:	2 cameras no video issue and 7th floor intercom off issue						
Technician Comment :	2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on off issue resoved and 7th floor reception intrcom issue resolved cantion side recontion						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on off issue resoved and 7th floor reception intrcom issue resolved cantion side recontion						
Status History :	Date Time	Technician Name	Status	Remark		Sign	
	03-08-2023 06:36:30	Siddhesh Chavan	Completed	2 camera no video issue resoved back side camera DC change and camera working ok and security cabin camera video on off issue resoved and 7th floor reception intrcom issue resolved cantion side recontion			
	03-08-2023 11:41:48	Siddhesh Chavan	New			-	
	01-08-2023 10:50:08	Siddhesh Chavan	New			-	
Previous Complain History :	Date Time	Technician Name	Remark				
	24-07-2023 12:27:24	DilshadKhan	All camera working done all camera Servicing done with ppm done				
	24-07-2023 12:24:56	YogeshDesai	New four channel power supply installed all camera are working ok. With proper recording				
	<u> </u>		working ok. V	vim broher re	corumy		