

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2045																																			
Priority :	High																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9833857590																																		
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																															
Ticket Type :	Complain	Date & Time :	19-10-2020 10:36:31																																
Vendor Details :																																			
Company Name/Client Name :	Kiran Tower	Customer's Mobile :	9833857590	Name :	Kalpesh Sir																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	30-06-2020 12:00:00		Type :	Non-Comprehensive																															
Product Name :	Intercom																																		
Complain :	intercom a wing-1301 b wing-1204,1302,901 office terrace																																		
Technician Comment :	crystal 16 line EXenation repaired return and install and display issue resolved and ok working																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	crystal 16 line EXenation repaired return and install and display issue resolved and ok working																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>24-10-2020 02:31:39</td><td>Ravi Rajbhar</td><td>Completed</td><td>crystal 16 line EXenation repaired return and install and display issue resolved and ok working</td><td></td></tr><tr><td>19-10-2020 06:41:01</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>A wing intercom 1301; 1201;1304exit 91 intercom issue resolved and ok working done b wing intercom flat no 1401 " 1201 " 902" 1204" 704" 1404 1302" and terrace both wing intercom check but one 16 line card missing in system</td><td></td></tr><tr><td>19-10-2020 11:12:59</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>19-10-2020 10:37:10</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>19-10-2020 10:36:31</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	24-10-2020 02:31:39	Ravi Rajbhar	Completed	crystal 16 line EXenation repaired return and install and display issue resolved and ok working		19-10-2020 06:41:01	Ravi Rajbhar	Work Pending	A wing intercom 1301; 1201;1304exit 91 intercom issue resolved and ok working done b wing intercom flat no 1401 " 1201 " 902" 1204" 704" 1404 1302" and terrace both wing intercom check but one 16 line card missing in system		19-10-2020 11:12:59	Ravi Rajbhar	New		-	19-10-2020 10:37:10	Ravi Rajbhar	New		-	19-10-2020 10:36:31	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																															
24-10-2020 02:31:39	Ravi Rajbhar	Completed	crystal 16 line EXenation repaired return and install and display issue resolved and ok working																																
19-10-2020 06:41:01	Ravi Rajbhar	Work Pending	A wing intercom 1301; 1201;1304exit 91 intercom issue resolved and ok working done b wing intercom flat no 1401 " 1201 " 902" 1204" 704" 1404 1302" and terrace both wing intercom check but one 16 line card missing in system																																
19-10-2020 11:12:59	Ravi Rajbhar	New		-																															
19-10-2020 10:37:10	Ravi Rajbhar	New		-																															
19-10-2020 10:36:31	Ravi Rajbhar	New		-																															

Previous Complain History :			
	Date Time	Technician Name	Remark
	16-10-2020 12:21:03	Siddhesh Chavan	dvr and flat side crimping done
	13-10-2020 10:23:36		arif visited 1301 a wing cable faulty b wing 1201 cable issue 1302 - duct to flat cable issue 901 - cable problem office cable problem 7776 cabin cable issue DSP problem a and b terrace system site crone problem