Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE3841 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9833857590 **No. :** Technician Neeraj Chauhan **Technician Mobile** 8898885764 Name : : **Ticket Type :** Complain Date & Time : 16-09-2021 03:46:39 **Vendor Details :** 9833857590 Company Kiran Tower Customer's Mobile Name : Kalpesh Sir Name/Client CHS Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 30-06-2020 12:00:00 Non-Comprehensive Expiry Date : Type : **Product Name :** CCTV **Complain**: Check 3 Mic working or not 2cameras terrace reinstalled and working ok 1301 63 meter cable use one snap used terrace Technician camera supply installed on 13 floor duct **Comment** : Complain Desktop - Apurva Vajaria **Operator** : 2cameras terrace reinstalled and working ok 1301 63 meter cable use one snap used terrace **Remark** : camera supply installed on 13 floor duct

Status History :	Date Time	Technician Name	Status		Remark	Sign
	18-09-2021 09:41:32	Neeraj Chauhan	Completed		2cameras terrace reinstalled and working ok 1301 63 meter cable use one snap used terrace camera supply installed on 13 floor duct	Sa-
	18-09-2021 06:06:27	Neeraj Chauhan	New			-
	17-09-2021 02:27:13	Neeraj Chauhan	Work Pending		3 mice check and two mic ok working done (office DVR) and b wing (mic cable check but one pair cable Breck) security tebal mic soldering issue with collat (and a wing one IP done camera remove and hondover to security and old anlage camera install same place angle setting pending	H (W/31
	17-09-2021 10:32:35	Neeraj Chauhan	New			-
	16-09-2021 03:46:50	Neeraj Chauhan	New			-
	16-09-2021 03:46:39	Neeraj Chauhan	New			-
Previous Complain History :	Date Time	Technician Name		Remark		
	02-08-2023 05:11:58	Kalpesh SubhashGurav		B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found		
	26-07-2023 10:03:17	Kalpesh SubhashGurav		B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK		