Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE5839 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9833857590 **No. : Technician** Ravi Rajbhar **Technician Mobile** 8080922965 Name : : Complain 01-07-2022 10:06:33 **Ticket Type : Date & Time : Vendor Details :** Kiran Tower Customer's Mobile 9833857590 Company Name : Kalpesh Sir Name/Client Name : **Address** : Mumbai,,,, Maharashtra **AMC Details :** 30-06-2020 12:00:00 Expiry Date : Type : Non-Comprehensive **Product Name :** cCTV-Intercom **Complain** : road side camera was offline and require intercom jack for punching , flat no b 1401 and 1403 intercom issue intercom big display issue resolved and ok working done **Technician Comment**: Desktop - Apurva Vajaria Complain **Operator** : **Remark** : intercom big display issue resolved and ok working done **Status History :** Date Time **Technician Name** Status Remark Sign 02-07-2022 11:14:06 Ravi Rajbhar Completed intercom big display issue resolved and ok working m/21 done 02-07-2022 10:49:52 Ravi Rajbhar New 01-07-2022 03:28:43 Ravi Rajbhar Work Pending b 1401 1403 102 intrcom issue resolved and kalpesh Th m/l2 sir flat cable nameing done and one 901 internet cable check and nameing done display issue pending 01-07-2022 10:07:07 Ravi Rajbhar New Ravi Rajbhar 01-07-2022 10:06:53 New _ 01-07-2022 10:06:33 Ravi Rajbhar New _

Previous Complain History :	Date Time	Technician Name	Remark
	28-06-2022 09:28:16	Ravi Rajbhar	one camera issue resolved only camera stand broken and temporary ok working and a 1404 cable missing flat to system b wing 1401 door lock
	03-06-2022 12:14:46	Atique Salmani	4 cameras angel settings done and one camera reconnection done becoz camer menu coming on screen and which one cameras not connected showing no vedeo hide this also all working ok. and one camer installation done given by kalpesh sir becoz it's a b wing dvr end camera so changed camera angel set all working ok.