Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE6244 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9833857590 **No. :** Technician Atique Salmani **Technician Mobile** 8080922984 Name : : Complain 25-08-2022 11:42:51 **Ticket Type :** Date & Time : **Vendor Details :** Company Kiran Tower Customer's Mobile 9833857590 Kalpesh Sir Name : Name/Client Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 30-06-2020 12:00:00 Type : Expiry Date : Non-Comprehensive **Product Name :** CCTV 1 new camera need to install and armoured cabling need to do **Complain**: 64 meter armour cabling done and camera last pole shop side working ok and old cable hand Technician **Comment** : over to client janak ji. Complain Desktop - Apurva Vajaria **Operator** : 64 meter armour cabling done and camera last pole shop side working ok and old cable hand **Remark** : over to client janak ji. **Status History :** Date Time **Technician Name** Status Remark Sign 26-08-2022 04:21:18 Atique Salmani Completed 64 meter armour cabling done and camera last pole shop side working ok and old cable hand over to client janak ji . 26-08-2022 10:15:20 Atique Salmani New 25-08-2022 11:43:03 Atique Salmani New 25-08-2022 11:42:51 Atique Salmani New

Previous Complain History :	Date Time	Technician Name	Remark
	20-08-2022 01:01:40	Atique Salmani	53mtrs of cabling done from b .wing dvr duct to shop spec lences Old cable of 35 mtrs also removed from the same shop. That cable is used for telephone line from sixth floor to ground floor telephone junction box cable used 30 mts. Pole IP camera armoured cable cut and rejoint again and working ok also confirm with kalpesh sir . Five rj 45 connector used
	21-07-2022 11:11:21	Ravi Rajbhar	flat no 1303 intercom issue solved intercom working ok . and main gate camera which was offline is now working camera cable cat six cable blue and green cable is break camera has been given separate power to work camera are working now can be seen online too.