

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6744																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9833857590																			
Technician Name :	Yogesh Desai		Technician Mobile :	8080922963																
Ticket Type :	Complain	Date & Time :	03-11-2022 01:23:51																	
Vendor Details :																				
Company Name/Client Name :	Kiran Tower	Customer's Mobile :	9833857590	Name :	Kalpesh Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	30-06-2020 12:00:00		Type :	Non-Comprehensive																
Product Name :	Intercom																			
Complain :	B/904 intercom issue																			
Technician Comment :	flat no b wing 904 mtnl line issue not intercom of society . society intercom working ok.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	flat no b wing 904 mtnl line issue not intercom of society . society intercom working ok.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-11-2022 02:47:27</td><td>YogeshDesai</td><td>Completed</td><td>flat no b wing 904 mtnl line issue not intercom of society . society intercom working ok.</td><td></td></tr><tr><td>03-11-2022 01:23:57</td><td>YogeshDesai</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-11-2022 02:47:27	YogeshDesai	Completed	flat no b wing 904 mtnl line issue not intercom of society . society intercom working ok.		03-11-2022 01:23:57	YogeshDesai	New		-
Date Time	Technician Name	Status	Remark	Sign																
03-11-2022 02:47:27	YogeshDesai	Completed	flat no b wing 904 mtnl line issue not intercom of society . society intercom working ok.																	
03-11-2022 01:23:57	YogeshDesai	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>13-10-2022 01:46:26</td><td>YogeshDesai</td><td>flat no 901 of b wing intercom issue solved intercom working ok. but ringer is very slow.</td></tr><tr><td>27-09-2022 10:24:05</td><td>Siddhesh Chavan</td><td>fire lift IP camera issue result and main gate TV brightness issue and switcher working OK TV issue from client site and 2 camera angle setting done</td></tr></tbody></table>					Date Time	Technician Name	Remark	13-10-2022 01:46:26	YogeshDesai	flat no 901 of b wing intercom issue solved intercom working ok. but ringer is very slow.	27-09-2022 10:24:05	Siddhesh Chavan	fire lift IP camera issue result and main gate TV brightness issue and switcher working OK TV issue from client site and 2 camera angle setting done						
Date Time	Technician Name	Remark																		
13-10-2022 01:46:26	YogeshDesai	flat no 901 of b wing intercom issue solved intercom working ok. but ringer is very slow.																		
27-09-2022 10:24:05	Siddhesh Chavan	fire lift IP camera issue result and main gate TV brightness issue and switcher working OK TV issue from client site and 2 camera angle setting done																		