## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Details : VE79							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	9833857590						
Technician Name :	Anil Yadav		Technician Mobile		8080922983		
Ticket Type :	New Installation	Date & Time:	17-08-2019 11:13:56				
Vendor Details :							
Company Name/Client Name :	Kiran Tower CHS	Customer's Mobile :	9833857590		Name :	Kalpesh Sir	
Address:							
Mumbai , , , , Maharashtra							
AMC Details :							
Expiry Date :	30-06-2020 12:00:0	0	Type:	Type:		Non-Comprehensive	
<b>Product Name:</b>	Fire						
Complain :	New Fire installation MCP						
Technician Comment :	A wing 14 MCP installed. all MCP new. B wing 14 MCP installed.13 old MCP and 2 new MCP. Both wing Fire panel working condition now.						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	A wing 14 MCP installed. all MCP new. B wing 14 MCP installed.13 old MCP and 2 new MCP. Both wing Fire panel working condition now.						
<b>Status History:</b>	Date Time	Technician Name	Status		Remark		Sign
	19-11-2019 05:26:18	AnilYadav	Completed	MCP nev installed new MC	4 MCP installed. al w. B wing 14 MCP .13 old MCP and 2 P. Both wing Fire orking condition now		Kil
	18-11-2019 12:16:51	AnilYadav	Work Pending				-
	18-11-2019 11:34:28	AnilYadav	New				-
	18-11-2019 11:33:55	AnilYadav	Completed				-
	26-08-2019 06:16:17	AnilYadav	In Progress	installed floor, Fin installati	r to 13 floor MCP working fine. grou est floor,14 floor MC ion pending. e given by. Janak		Mz:K
	17-08-2019 05:17:43	AnilYadav	Work Pending		fire panel installati t need to check	ion	Jul
	17-08-2019 11:13:57	AnilYadav	New				-

<b>Previous</b>
<b>Complain</b>
<b>History</b> :

Date Time	Technician Name	Remark			
02-08-2023 05:11:58 Kalpesh SubhashGurav		B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found			
26-07-2023 10:03:17 Kalpesh SubhashGurav		B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK			