## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Sarvica Status Do	taile • VF8000									
Service Status Details : VE8000										
Priority:	Low									
Created By:	Admin - Apurva Vajaria									
Complaint Mob. No. :	9833857590									
Technician Name :	Santosh Pathak			<b>Te</b> :	Technician Mobile 8080922980					
Ticket Type :	Complain Date & Tim		& Time:	30-03-2023 10:26:39						
Vendor Details :										
Company Name/Client Name :	Kiran Tower	Custon:	mer's Mobile	9833857590			Name :	Kalpesh Sir		
Address:										
Mumbai , , , , Mal	harashtra									
AMC Details :										
Expiry Date :	30-06-2020 12:00:00			Ту	Type:		Non-Comprehensive			
<b>Product Name:</b>	Intercom									
Complain:	4 lift intercom phone need to install									
Technician Comment :	A wing lift no 1 and 2 intercom phone installed and b wing pending and 2phone handover to kailash ji									
Complain Operator :	Desktop - Apurva Vajaria									
Remark:	A wing lift no 1 and 2 intercom phone installed and b wing pending and 2phone handover to kailash ji Bldg lift 1 beetel telephone installed done working properly									
Status History :	Date Time		Technician Name		Status	Remark		T	Sign	
	08-04-2023 01:16:42		SantoshPathak		Completed				-	
	31-03-2023 11:26:54		SantoshPathal	ζ	New					
	31-03-2023 10:25:27	31-03-2023 10:25:27		2	New				-	
	30-03-2023 11:27:42		SantoshPathak		Work Pending	A wing lift no 1 and intercom phone installed and b wing pending and 2phone handover to kailash			Bythaly	
	30-03-2023 10:27:28		SantoshPathak		New				-	
Previous	Date Time Technician Nam		chnician Name	Remark						
Complain History :	29-03-2023 02:17:47	_	SantoshPathak		Kalpesh visited on 29.03.2023 - B/1003 new connection done working properly.					
	23-03-2023 02:47:03	3 So	nu Kumar	Kiran tower b wing 4 camera off issue resolved working ok 3 BNC connector used and a wing 1 camera off issue resolved working ok						