




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE807																														
Priority :	High																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9833857590																													
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																										
Ticket Type :	New Installation	Date & Time :	17-12-2019 04:14:20																											
Vendor Details :																														
Company Name/Client Name :	Kiran Tower CHS	Customer's Mobile :	9833857590	Name :	Kalpesh Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	30-06-2020 12:00:00		Type :	Non-Comprehensive																										
Product Name :	Intercom																													
Complain :	need to give 2 phone																													
Technician Comment :	502 bwing 1instrument installed and working ok and 1instrument handover to mr kailash security supervisor.																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	502 bwing 1instrument installed and working ok and 1instrument handover to mr kailash security supervisor.																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>20-02-2020 09:58:14</td><td>Atique Salmani</td><td>Completed</td><td>502 bwing 1instrument installed and working ok and 1instrument handover to mr kailash security supervisor.</td><td></td></tr><tr><td>20-02-2020 09:56:04</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>05-02-2020 03:51:04</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>17-12-2019 04:14:21</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	20-02-2020 09:58:14	Atique Salmani	Completed	502 bwing 1instrument installed and working ok and 1instrument handover to mr kailash security supervisor.		20-02-2020 09:56:04	Atique Salmani	New		-	05-02-2020 03:51:04	Atique Salmani	New		-	17-12-2019 04:14:21	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																										
20-02-2020 09:58:14	Atique Salmani	Completed	502 bwing 1instrument installed and working ok and 1instrument handover to mr kailash security supervisor.																											
20-02-2020 09:56:04	Atique Salmani	New		-																										
05-02-2020 03:51:04	Atique Salmani	New		-																										
17-12-2019 04:14:21	Atique Salmani	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>02-08-2023 05:11:58</td><td>Kalpesh SubhashGurav</td><td>B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found</td></tr><tr><td>26-07-2023 10:03:17</td><td>Kalpesh SubhashGurav</td><td>B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK</td></tr></tbody></table>					Date Time	Technician Name	Remark	02-08-2023 05:11:58	Kalpesh SubhashGurav	B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found	26-07-2023 10:03:17	Kalpesh SubhashGurav	B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK																
Date Time	Technician Name	Remark																												
02-08-2023 05:11:58	Kalpesh SubhashGurav	B Wing Lift no.2 intercom issue solved Intercom line running in Duct flat to Duct cable not found																												
26-07-2023 10:03:17	Kalpesh SubhashGurav	B Wing Lift No. 1 Intercom Problem Solved. A And B Wing Both Lift Intercom Checking Done. A/ 1203 OK B/ 1205 OK																												