

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8480																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9833857590																			
Technician Name :	Munna Gupta		Technician Mobile :	8080922982																
Ticket Type :	Complain	Date & Time :	02-06-2023 12:13:08																	
Vendor Details :																				
Company Name/Client Name :	Kiran Tower CHS	Customer's Mobile :	9833857590	Name :	Kalpesh Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	30-06-2020 12:00:00		Type :	Non-Comprehensive																
Product Name :	Intercom																			
Complain :	A-1203, B-1301, B-1403, B-1004 intercom issue																			
Technician Comment :	intercom system mein kisi bhi extension mein phone mein ring nahin baj raha hai. intercom system mein power supply ka problem hai.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	intercom system mein kisi bhi extension mein phone mein ring nahin baj raha hai. intercom system mein power supply ka problem hai.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-06-2023 04:15:02</td><td>Munna Gupta</td><td>Completed</td><td>intercom system mein kisi bhi extension mein phone mein ring nahin baj raha hai. intercom system mein power supply ka problem hai.</td><td></td></tr><tr><td>02-06-2023 12:13:16</td><td>Munna Gupta</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-06-2023 04:15:02	Munna Gupta	Completed	intercom system mein kisi bhi extension mein phone mein ring nahin baj raha hai. intercom system mein power supply ka problem hai.		02-06-2023 12:13:16	Munna Gupta	New		-
Date Time	Technician Name	Status	Remark	Sign																
02-06-2023 04:15:02	Munna Gupta	Completed	intercom system mein kisi bhi extension mein phone mein ring nahin baj raha hai. intercom system mein power supply ka problem hai.																	
02-06-2023 12:13:16	Munna Gupta	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>12-06-2023 12:00:29</td><td>Ishwar Meena</td><td>(1) B wing Graund floor lift side new bullet camera installed. (2)shop side one Ip bullet old camera installed.</td></tr><tr><td>07-06-2023 10:38:21</td><td>Kalpesh SubhashGurav</td><td>New Crystal Power supply Installed OK A/1203 - New Telephone Required B1301 - OK Main Gate Security Required Extra Ringer</td></tr></tbody></table>					Date Time	Technician Name	Remark	12-06-2023 12:00:29	Ishwar Meena	(1) B wing Graund floor lift side new bullet camera installed. (2)shop side one Ip bullet old camera installed.	07-06-2023 10:38:21	Kalpesh SubhashGurav	New Crystal Power supply Installed OK A/1203 - New Telephone Required B1301 - OK Main Gate Security Required Extra Ringer						
Date Time	Technician Name	Remark																		
12-06-2023 12:00:29	Ishwar Meena	(1) B wing Graund floor lift side new bullet camera installed. (2)shop side one Ip bullet old camera installed.																		
07-06-2023 10:38:21	Kalpesh SubhashGurav	New Crystal Power supply Installed OK A/1203 - New Telephone Required B1301 - OK Main Gate Security Required Extra Ringer																		